

**Continental Cement Co., L.L.C.**

10107 Hwy 79 So  
Hannibal, MO 63401  
Phone 573-221-1740  
Fax 573-221-1689

December 31, 2011

Attn: Edward L. Kulzer CIH, CSP

Health Physicist

United States Nuclear Regulatory Commission Region III

2443 Warrenville Road, Suite 210

Lisle, Illinois 60532-4352

30 Day Corrective Action Follow-up Report

Dear Mr. Kulzer,

This is a follow-up letter to confirm the corrective actions that were taken in response to the "stuck shutter" incident on December 8, 2010 at Continental Cement Company L.L.C. The following actions have been taken:

Short Term: General maintenance (cleaning of clinker dust) was performed on the Berthold Technologies Model PB100 weigh belt on January 11, 2011 to ensure that the shutter will now fully open and close.


Long Term: The Continental Cement LLC Nuclear Safety Program was modified to include:

- Changes to the procurement section to include a review of license possession limits prior to ordering of any new materials and.
- Sending a copy of the current Specific License Amendment to the material provider prior to purchasing.

In addition, a memo outlining these changes has been sent to all management personnel. A copy of this report has been placed in the annual safety program audit file, and. The annual safety audit will be changed to ensure a memo of the same nature is sent to management personnel each year during the audit.

Please contact me if any of these changes are not to your approval or if additional changes are needed.

Sincerely,



William E. Sherman Jr./RSO