



FEB 7 2011

L-2011-042
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-00001

Re: Turkey Point Unit 3
Docket No. 50-250
Inservice Inspection Program
Fourth Interval-Second Period-Third Refueling Outage
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 3 Fourth Inservice Inspection Interval, Second Period, Third Refueling Outage (PTN 3-25). The Form OAR-1, Owner's Activity Report, implements Code Case N-532-4.

Should there be any questions concerning this report, please contact Robert J. Tomonto at 305-246-7327.

Very truly yours,

Paul W. Rubin
Michael Kiley

Michael Kiley
Vice President
Turkey Point Nuclear Plant

SM

Attachment

A047
NRK

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-PTN-3-2010

Plant: Turkey Point Nuclear Power Plant Unit 3
P.O. Box 4332
Florida City, Florida 33032

Commercial Service Date: December 14, 1972 Refueling Outage No.: PTN 3-25

Current Inspection Interval: ISI-Fourth IWE-Second Current Inspection Period: ISI-Second IWE-First

Edition and Addenda of Section XI applicable to the inspection plans: ISI-1998 Edition with Addenda through 2000 and IWE-2001 with Addenda through 2003.

Date and Revision of inspection plans: ISI-July 23, 2010, Rev .3 IWE-March 3, 2009, Rev. 0

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan:
Same

Code Cases Used: N-460, N-532-4, N-533-1, N-566-1, N-624, N-686, N-513-2

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN 3-25 conform to the requirements of Section XI.

Signed Glenn P. Olcott FOR R.D.GIL - ENG. PROGRAMS Date 2/3/11
Owner or Owner's Designee, Title MANAGER

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Florida and employed by HSBCT of Hartford Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with: the requirements of Section XI.

By signing this certificate, neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

John A. Olcott Commissions FL 477 (A, C, N, I)
Inspector's Signature National Board, State, Province, and Endorsements

Date 2-7-2011

FORM OAR-1 OWNER'S ACTIVITY REPORT

**TABLE 1
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED
EVALUATION FOR CONTINUED SERVICE**

Examination Category and Item Number	Item Description	Evaluation Description
D-B/D2.10	8" Pipe Upstream of Valve 3-910	Evaluate for continued service with thru-wall leak until leak is addressed. See Table 2 for Repair
D-B/D2.10	4" Pipe Upstream of 3-12-028	Evaluate for continued service with thru-wall leak until leak is addressed. See Table 2 for Repair
D-B/D2.10	4" Pipe Upstream of 3-12-028	Evaluate for continued service with thru-wall leak until leak is addressed. See Table 2 for Replacement
D-B/D2.10	4" Pipe Downstream of 3-12-029	Evaluate for continued service with thru-wall leak until leak is addressed. See Table 2 for Replacement

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2				
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
2	Reactor Sump Containment Liner	Replace Corroded section of Liner plate	11/1/10	RR40049244-05
2	Pipe down steam of Valve 3-20-132	Replace section of pipe due to external corrosion	11/4/10	RR40035857-09
2	Support 7883-H-013	Repair corroded trunion (Integral Attachment)	10/29/10	RR40046100-01
3	Pipe upstream of Valve 3-12-028	Repair pipe with thru-wall leak due to external corrosion.	4/17/10	RR40002240-06
3	Pipe upstream of Valve 3-910	Repair pipe with thru-wall leak due to external corrosion.	2/15/10	RR39016861-01
3	Valves 3-12-028 and 3-12-029	Replace pipe with thru-wall leaks due to external corrosion	12/30/10	RR40002240-04
3	Condensate Storage Tank	Weld Buildup on corroded tank	1/26/10	RR39016774-01