

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8102250663. DOC.DATE: 81/02/20 NOTARIZED: NO DOCKET #
 FACIL:50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439

AUTH.NAME AUTHOR AFFILIATION
 MILLS,L.M. Tennessee Valley Authority
 RECIP.NAME RECIPIENT AFFILIATION
 O'REILLY,J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Fourth interim deficiency rept,initially reported 800415, re welding of structural steel annulus floor framing.After categorizing welds sampling techniques of MIL-Std 1050 will be used to determine initial sample space for reinsp.

DISTRIBUTION CODE: B019S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	YOUNGBLOOD,B 05	1	1
	RUSHBROOK,M. 06	1	1	BOURNIA,T. 07	1	1
INTERNAL:	AD/RCI/IE 17	1	1	ASLBP/J.HARD	1	1
	D/DIR HUM FAC15	1	1	DIR,DIV OF LIC	1	1
	EDO & STAFF 19	1	1	EQUIP QUAL BR11	1	1
	HYD/GEO BR 22	1	1	I&E 09	1	1
	LIC QUAL BR 12	1	1	MPA 20	1	1
	NRC PDR 02	1	1	OELD 21	1	1
	PROC/TST REV 13	1	1	QA BR 14	1	1
	<u>REG FILE</u> 01	1	1	RUTHERFORD,W,IE	1	1
	STANDRDS DEV 21	1	1			
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

FEB 27 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 39

400 Chestnut Street Tower II

February 20, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 2 - WELDING OF STRUCTURAL STEEL ANNULUS FLOOR
FRAMING - NCR 1173 - FOURTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector R. W. Wright on April 15, 1980, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated May 15, July 30, and November 7, 1980. Enclosed is our fourth interim report. We expect to submit our next written report by June 23, 1981.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/1

S 810225 663

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 2
WELDING OF STRUCTURAL STEEL ANNULUS FLOOR FRAMING
NCR 1173
10 CFR 50.55(e)
FOURTH INTERIM REPORT

Description of Deficiency

The welding inspector completed visual inspection records for welds of structural steel annulus floor framing before the welds had been made.

Interim Progress

TVA has finalized its record search to identify inspections for which the welding inspector was responsible. After categorizing the welds identified, the sampling techniques of MIL-Standard 105D will be used to determine the initial sample space for reinspection.