

MAI, JWA

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8005200618 DOC. DATE: 80/05/16 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards first interim deficiency rept re lack of internal purge on two welds in chemical addition & boron recovery sys.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: -----

| | RECIPIENT ID CODE/NAME | COPIES | | RECIPIENT ID CODE/NAME | COPIES | |
|-----------|---------------------------|---------|------|---------------------------|---------|------|
| | | LTR | ENCL | | LTR | ENCL |
| ACTION: | 14 PM BOURNIA | 1 | 1 | 15 BC LWR #3 | 1 | 1 |
| | 20 LA LWR #3 | 1 | 1 | 21 AD LWR | 1 | 1 |
| INTERNAL: | 01 REG FILE | 1 | 1 | 02 NRC PDR | 1 | 1 |
| | 05 I&E | 2 | 2 | 07 EDO & STAFF | 1 | 1 |
| | 08 MPA | 1 | 1 | 09 DEPY DIR DPM | 1 | 1 |
| | 10 QAB | 1 | 1 | 11 STANDROS DEV | 1 | 1 |
| | 13 FIELD COUR/IE | 1 | 1 | 16 AD FOR ENGR | 1 | 1 |
| | 17 AD PLANT SYS | 1 | 1 | 17 AD REAC SFTY | 1 | 1 |
| | 22 DIR DPM | 1 | 1 | 23 OELD | 1 | 1 |
| | AD/RCI/IE | 1 | 1 | AD/SITE TECH | 1 | 1 |
| | AEOD | 1 | 1 | DIRECTOR DSE | 1 | 1 |
| | GEOSCIENCES BR | 1 | 1 | HANAUER, S. | 1 | 1 |
| | I&C SYS BR | 1 | 1 | MATL ENG BR | 1 | 1 |
| | MECH ENG BR | 1 | 1 | POWER SYS BR | 1 | 1 |
| | STRUCT ENG BR | 1 | 1 | | | |
| | EXTERNAL: | 03 LPDR | 1 | 1 | 04 NSIC | 1 |
| 24 ACRS | | 16 | 16 | | | |

8005200618
5

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

May 16, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - LACK OF INTERNAL PURGE ON
TWO WELDS IN CHEMICAL ADDITION AND BORON RECOVERY SYSTEM - NCR 1171 -
FIRST INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector
J. D. Wilcox on April 17, 1980, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next
written report by July 23, 1980.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S/11