

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: J.G.KEBBER

FROM: WISCONSIN PUBLIC SVC. CORP.  
GREEN BAY, WISCONSIN  
E.W.JAMES

DATE OF DOCUMENT  
3/4/77

DATE RECEIVED  
3/7/77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP ... IMPUT FORM

NUMBER OF COPIES RECEIVED  
1 SIGNED CY. RECEIVED

DESCRIPTION

LTR. TRANS THE FOLLOWING.....

ENCLOSURE

LICENSEE EVENT RPT # 77-7, ON 2/18/77 CONCERNING THE SEALS ON THE DOOR ACTUATING SHAFTS ON THE OUTER DOOR WERE FOUND TO BE LEAKING IN EXCESS OF THE TESTER MEASURING CAPABILITY.....

(1P)(2P)  
(1 CY RECEIVED)

**DO NOT REMOVE**  
**ACKNOWLEDGED**

PLANT NAME: KEWAUNEE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION SAB 3/11/77

<input checked="" type="checkbox"/>	BRANCH CHIEF:	SCHWENCER	
	W/3 CYS FOR ACTION		
<input checked="" type="checkbox"/>	LIC. ASST.:	SHEPPARD	
	W/ CYS		
<input checked="" type="checkbox"/>	ACRS 16 CYS <del>XXXXXX</del> SENT CAT "B"		

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	<u>REG FILE</u>		
<input checked="" type="checkbox"/>	NRC PDR		
<input checked="" type="checkbox"/>	I & E (2)		
<input checked="" type="checkbox"/>	MIPC		
<input checked="" type="checkbox"/>	SCHROEDER/IPPOLITO		
<input checked="" type="checkbox"/>	HOUSTON		
<input checked="" type="checkbox"/>	NOVAK/CHECK		
<input checked="" type="checkbox"/>	GRIMES		
<input checked="" type="checkbox"/>	CASE		
<input checked="" type="checkbox"/>	BUTLER		
<input checked="" type="checkbox"/>	HANAUER		
<input checked="" type="checkbox"/>	TEDESCO/MACCARY		
<input checked="" type="checkbox"/>	EISENHUT		
<input checked="" type="checkbox"/>	BAER		
<input checked="" type="checkbox"/>	SHAO		
<input checked="" type="checkbox"/>	VOLLMER/BUNCH		
<input checked="" type="checkbox"/>	KREGER/J. COLLINS		

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/>	LPDR: KEWAUNEE, WIS		
<input checked="" type="checkbox"/>	TIC:		
<input checked="" type="checkbox"/>	NSIC:		

2458  
305  
A04  
GD

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305



March 4, 1977



Mr. J. G. Keppler, Regional Director  
Office of Inspection & Enforcement  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Subject: Docket 50-305  
Operating License DPR-43  
Reportable Occurrence

In accordance with the requirements of Technical Specifications, Section 6.9.2.b, the attached Licensee Event Report for reportable occurrence RO 77-7 is being submitted. Initially, this report was transmitted via telegram in 24 hours in accordance with Section 6.9.2.a of Technical Specifications. However, after reviewing the information available, this incident has been reevaluated to be a reduction in the degree of redundancy provided by this safety feature and, therefore, reportable as a 30-day reportable occurrence in accordance with Technical Specifications, Section 6.9.2.b. We have discussed this reevaluation with Mr. Hunter of your office via telephone on March 1, 1977.

Very truly yours,

E. W. James  
Senior Vice President  
Power Supply & Engineering

EWJ:sna  
Enc.

cc - Dir, Office of Inspection & Enforcement  
US NRC, Washington, D. C. 20555  
Dir, Office of Management Info & Program Control  
US NRC, Washington, D. C. 20555



Event Description (Cont.)

are kept shut except during the brief period of time someone is entering or exiting containment, thus during an accident the one door would have been able to maintain the integrity of the containment boundary within the acceptance criteria specified in section 4.4 of Technical Specifications. (RO 77-7)