CONTROL NO: 8325

FILE	:	

FROM:			DATE OF DOC	DATE	REC'D	LTR	TWX	RPT	OTHER
Wiscons	in Public Se	ervice Corp		1		•	· ·		
Green B	ay, WI	•					İ		Ì
CR Luon	ia?	· · · · · · · · · · · · · · · · · · ·	8-7-74	8-	12-74		Х		1
TO:		έ.	ORIG .	CC	OTHER		SENT	AEC PDR	XXX
Dwa	ne Boyd	•	1		1		SENT :	LOCAL P	DR XXX
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D			DOCKET NO:		
	İ			1			1		
:	XXX	L		1	1		50-305		
BROODE	OMT ONL			23302	20170				

DESCRIPTION:

Twx furn info re abnormal occurrence #50-305/74-11 of 7-22-74 re one fan coil unit out of service....

ENCLOSURES:

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: KEWAUNEE

		FOR ACTION/INFOR	MATION 8-13-7	74 GMC
W/ CYS CLARK (L) W/ CYS TIME (L) W/ CYS	SCHWENCER (L) W/7 CYS STOLZ (L) W/ CYS WASSALLO (L) W/ CYS	ZIEMANN (L) W/ CYS DICKER (E) W/ CYS MNICHTON (E) W/ CYS	REGAN (E) W/ CYS LEAR W/ CYS W/ CYS	
KNIEL (L) W/ CYS	PURPLE (L) W/ CYS	YOUNGBLOOD (E W/ CYS	W/ CYS	
		INTERNAL DISTRIBUT	ION	
REG FILE AEC PDRI OGC MUNTZING/STAFF CASE GIAMBUSSO BOYD MOORE (L)(LWR-2) DEYOUNG (L)(LWR-1 SKOVHOLT (L)	TECH REVIEW HENDRIE SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER	LIC ASST DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L)	PLANS MCDONALD CHAPMAN DUBE w/input
GOLLER (L) P. COLLINS DENISE REG OPR FILE & REGION (3)	ROSS IPPOLITO TEDESCO LONG	DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT MGR	SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	D. THOMPSON (2) KLECKER EISENHUT

HARLESS

EXTERNAL DISTRIBUTION

- LOCAL PDR KEWAUNEE, WI

- TIC

(ABERNATHY) (1)(2)(10)-NATIONAL LABS

1 - NSIC (BUCHANAN)

1 - ASLB

1 - P. R. DAVIS

MORRIS

- ACRS SENT TO LIC ASSTGOULBOURNE 8-13 1-CONSULTANTS

✓BENAROYA

VOLLMER

1-B&M SWINEBROAD, Rm E-201 GT 1-AGMED (RUTH GUSSMAN)

NEWMARK/BLUME/AGBABIAN

1-ASLBP(E/W Bldg, Rm 529)

1-PDR-SAN/LA/NY

1-BROOKHAVEN NAT LAB

1-W. PENNINGTON, Rm E-201 GT 1-G. ULRIKSON, ORNL

Rm B-127 GT

1-RD..MUELLER, Ram F-309

GT

TELEGRAM

Mr. Dwane Boyd Resident Inspector - Atomic Energy Commission Directorate of Regulatory Operations Region III Two Rivers Municipal Hospital Two Rivers, Wisconsin

SUBJECT: Docket 50-305

Operating License DPR-43 Abnormal Occurrence Report

In accordance with the requirements of Technical Specifications, Paragraph 6.6.2.a, 1.0a.1.(b) and 3.3.b.2.A, we submit the following:

Report Number: 50-305/74-11

Occurrence Date: July 22, 1974 1540

Facility: Kewaunee Nuclear Power Plant

Kewaunee, Wisconsin

Identification of Occurrence: One fan coil unit out of service

Conditions Prior to Occurrence: Reactor Critical - 93% Power

Normal Operating Temperature 560°F System Operating Pressure - 2226 psig

Description of Occurrence:

Control Operator attempted to open a service water return valve on one fan coil unit, from the control room. Valve would not open due to thermal overloads having opened the circuit preventing valve from opening. It was discovered that the installed heaters were to small, causing the thermal overloads. The Tech. Spec. requirement (Para. 3.3.b.2.A) is to have the fan coil unit in operation within seven days. Larger heaters were in stock which were used to get the valve and fan coil unit back into service. The reason that the seven days was exceeded, was that the replacement of heaters was being done on a design change request and administrative procedures neglected to point out the seven day requirement. The fan coil was placed in service on August 6th.

cc: Mr. J. F. O'Leary - Director
Directorate of Licensing

CRquona