DOCKET NBR: 050-305	KEWAUNEE	DOC DATE:	781018				
RECIPIENT: <u>KEPPLER, J.G.</u> ORIGINATOR: <u>JAMES, E.W.</u> COMPANY NAME:WI PUB SVC		ACCESSION NBR: 7810240128 COPIES RECEIVED: LTR 1 ENCL 1					
				SUBJECT:			
					700010 6		mod on the diashang
LER#78-031/03L-0 on (22D)							
of coolant pump (CCP							
TS 3.2.c.l. Crack in	n CCP IC was cat	<u>ised by oper str</u>	ess & vibration load				
	· · · · · · · · · · · · · · · · · · ·		·····				
- · · ·	·						
DISTRIBUTION CODE:	2004		NOTARIZED				
DISTRIBUTION TITLE:	•						
INCIDENT REPORTS							
NAME	ENCL?	FOR ACTION					
BREHIFF	W/4 ENCL	• ORB#1 BC					
REG FILE	W/ENCL						
I & E	W/ENCL W/3 ENCL						
MIPC	W/3 ENCL	.					
I & C SYSTEMS BR	WZENCL						
EMERGENCY PLAN BR NDVAK/CHECK	W/ENCL W/ENCL						
EEB	W/ENCL						
AD FOR ENG	W/ENCL	:					
PLANT SYSTEMS BR	W/ENCL	i					
HANAUER	WZENCL						
AD FOR PLANT SYSTEMS	S W/ENCL W/ENCL	1					
AD FOR SYS & PROJ REACTOR SAFETY BR	W/ENCL	· · ·					
ENGINEERING BR	WZENCL	· ·					
VOLLMER/BUNCH	W/ENCL						
KREGER/J. COLLINS	W/ENCL						
POWER SYS BR	W/ENCL						
K SEYFRIT/IE	W/ENCL						
LPDR	W/ENCL		<i>.</i>				
NSIC	W/ENCL W/16 ENCL	•					
ACRS							
TOTAL NUMBER OF CO	OPIES REQUIRED:	A A					
· ·	L TR Encl	44					
			i i i i i i i i i i i i i i i i i i i				
	•						
*							

·

.

• •

Ao 4 GD

D. Lanham

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

October 18, 1978

Mr. J. G. Keppler, Regional Director Office of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 Reportable Occurrence LER 78-031/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-031/03L-0 is being submitted.

Very truly yours,

E. W. James Senior Vice President Power Supply & Engineering

 snf

Attach.

cc - Dir, Office of Inspection & Enforcement US NRC, Washington, D. C. 20555 Dir, Office of Mgt Info & Program Control US NRC, Washington, D. C. 20555

1902|s 11, OCT 20 1978

dupe: 781924 \$128

(7-77),	
and the second sec	CONTROL BLOCK:
	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 0 5 0 0 9 1 8 7 8 8 1 0 1 8 7 8 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02	During steady full power operation, a small leak was discovered on the discharge of
03	coolant charging pump (CCP) 1C. At this time, CCP 1B was out of service for
04	maintenance on its varidrive unit, therefore, the facility was under LCO TS 3.2.c.l.
05	CCP 1B was returned to service three hours later, within the time allowed by the
06	TS LCO. Since one CCP provides all the capacity normally required, there was no
07	effect on plant operation or public safety.
08 78	SYSTEM CAUSE CAUSE COMP. VALVE
09 7 B	$ \begin{array}{c} CODE \\ P \\ \hline C \\ 9 \\ \hline 10 \\ \hline 11 \\ \hline 11 \\ \hline 12 \\ \hline 12 \\ \hline 12 \\ \hline 12 \\ \hline 13 \\ \hline 18 \\ \hline 18 \\ \hline 18 \\ \hline 18 \\ \hline 19 \\ \hline 10 \\ \hline$
10	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	block. The crack was caused by operating stress and vibration loads. The weld was
12	ground out and the discharge line flange was aligned and re-welded. Dye penetrant
13	checks of the first pass and cap welds were satisfactory. No further action is
$\begin{bmatrix} 1 & 4 \\ 7 & 8 \end{bmatrix}$	considered necessary.
F 15 7 8	ACILITY STATUS % POWER OTHER STATUS 30 METHOD OF E 28 1 0 0 29 NA A 31 Operator Observation 32 9 10 12 13 44 45 46 80
	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA 9 3 10 11 44 45 LOCATION OF RELEASE 36 NA 80
$\begin{bmatrix} 1 & 7 \\ 7 & 8 \end{bmatrix}$	
1 8	
	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) NA
20	PUBLICITY NRC USE ONLY SSUED DESCRIPTION (45) N (44) NA (11) 9 10
	NAME OF PREPARER G, H, Ruiter PHONE: (414) 433-1329

WISCONSIN PUBLIC SERVICE CORPORATION



41 - 14 - E

P.O. Box 1200, Green Bay, Wiscansin 54305

October 18, 1978

Mr. J. G. Keppler, Regional Director Office of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 Reportable Occurrence LER 78-031/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-031/03L-0 is being submitted.

Very truly yours,

State Anna - 1

E. W. James Senior Vice President Power Supply & Engineering

mf

La cara a -

Attach.

cc - Dir, Office of Inspection & Enforcement US NRC, Washington, D. C. 20555 Dir, Office of Mgt Info & Program Control US NRC, Washington, D. C. 20555

7810240128