Central files

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

April 16, 1979

Mr. J. G. Keppler, Regional Director Office of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Gentlemen:

Docket 50-305 Operating License DPR-43 IE Bulletin No. 79-03

IE Bulletin addresses longitudinal weld defects in SA-312 type 304 stainless steel pipe manufactured by Youngstown Welding & Engineering Company.

An investigation of the piping records at the Kewaumee Nuclear Power Plant has revealed that welded seam pipe manufactured by Youngstown Welding and Engineering Company was not employed in fabrication of safety related systems at Kewaumee.

As a result of this investigation no further action is necessary.

Very truly yours,

E. R. Mathews Vice President

Power Supply & Engineering

d1

cc: Dir, Office of Inspection & Enforcement US NRC, Washington, DC 20555

7905290501

po V