

F 04/27/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-305

REC: KEPPLER J G
NRC

ORG: JAMES E W
WI PUB SVC

DOCDATE: 04/20/78
DATE RCVD: 04/26/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-305/78-012/03L-0) ON 03/21/78
CONCERNING UPON COMPLETION OF THE MONTHLY D/G FOUR-HOUR RUN SURVEILLANCE
TEST, THE D/G SOURCE BREAKER COULD NOT BE TRIPPED FROM THE CONTROL PANEL... A
FAILED TRIP COIL CAUSED THE BREAKER FAILURE.

PLANT NAME: KEWAUNEE

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: *nl*

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:

1. SEND 4 COPIES OF ALL MATERIAL TO I&E
2. LAWRENCE(OELD) - 1 COPY ALL MATERIAL

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF SCHWENCER**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL

I & E**W/2 ENCL
SCHROEDER/IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAD**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
HOUSTON**W/ENCL
EEB**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL:

LPDR'S
KEWAUNEE, WI**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P

CONTROL NBR: 781170089

Ro 4

***** THE END *****

D. Sanham

FILE

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

April 20, 1978

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 78-012/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-012/03L-0 is being submitted.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

sa

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, D. C. 20555

APR 24 1978

AO 4
GP

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 25 30 37 38 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58
 0 1 W I K N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58
 7 8 9 14 15 25 25 30 37 38 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58
 0 1 L 5 0 5 0 0 0 3 0 5 7 0 3 2 1 7 8 8 0 4 2 0 7 8 9
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady full power operation the monthly D/G four-hour run surveillance test

0 3 | was conducted. Upon completion of the test the D/G source breaker could not be

0 4 | tripped from the control panel and had to be tripped locally. Since the breaker trip

0 5 | function is safeguards related, this placed the facility under LCO TS 3.7.b.2. The

0 6 | other D/G and offsite power sources remained operable; therefore, there was no effect

0 7 | on plant operation or public safety.

7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0	9	E	E	E		A		C	K	T	B	R	K	A	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	
(17) LED TO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
7 8		7 8		0 1 2		0 3		L		0					
21 22		23 24		25 26		27 28		29 30		31 32					
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z		Z		0 0 0 0	N	Y	A	M	1	7	5		
23 24	25 26	27 28	29 30	31 32	33 34	35 36	37 38	39 40	41 42	43 44	45 46	47 48	49 50	51 52	53 54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A failed trip coil caused the breaker failure. The breaker was replaced with

1 1 | a spare and the D/G was tested and returned to service. The defective trip coil was

1 2 | replaced and the breaker was tested satisfactorily. The trip coil failed with

1 3 | an open circuit. This is the first occurrence of this type. No further action is

1 4 | necessary.

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 E (28) 1 0 0 (29) NA B (31) Surveillance Testing 80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	37	Z	39	NA	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	2	0	0
0	0	0	40
		NA	

8		9		11		12	
		LOSS OF OR DAMAGE TO FACILITY				(43)	
		TYPE		DESCRIPTION			
1	9	Z	(42)	NA			

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA

NRC USE ONLY

NAME OF PREPARER G. H. Ruiter

PHONE: (414) 433-1329

WISCONSIN PUBLIC SERVICE CORPORATION

Public Service

P.O. Box 1200, Green Bay, Wisconsin 54305

US NRC
DISTRICT SERVICES
CHARGE

978 APR 26 AM 10 33

REGISTRATION
SERVICES UNIT

April 20, 1978

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


REGULATORY DOCKET FILE COPY

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 78-012/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-012/03L-0 is being submitted.

Very truly yours,



E. W. James
Senior Vice President
Power Supply & Engineering

sa

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, D. C. 20555

781170089

1002
5/11

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	W I K N P 1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5																																																															
7 8		9 14		15		25		26		30		57		CAT		58				5																																																																
CON'T																																																																																				
0	1	REPORT SOURCE		L	6	0	5	0	0	0	3	0	5	7	0	3	2	1	7	8	8	0	4	2	0	7	8	9																																																								
7 8		60 61		68		69		EVENT DATE		74		75		REPORT DATE		80																																																																				
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																																																																																				
0 2		During steady full power operation the monthly D/G four-hour run surveillance test																																																																																		
0 3		was conducted. Upon completion of the test the D/G source breaker could not be																																																																																		
0 4		tripped from the control panel and had to be tripped locally. Since the breaker trip																																																																																		
0 5		function is safeguards related, this placed the facility under LCO TS 3.7.b.2. The																																																																																		
0 6		other D/G and offsite power sources remained operable; therefore, there was no effect																																																																																		
0 7		on plant operation or public safety.																																																																																		
0 8																																																																																				
7 8 9																																																																																				
0 9																																																																																				
7 8																																																																																				
<table border="0" style="width:100%;"> <tr> <td style="width:15%;">SYSTEM CODE</td> <td style="width:15%;">CAUSE CODE</td> <td style="width:15%;">CAUSE SUBCODE</td> <td style="width:15%;">COMPONENT CODE</td> <td style="width:15%;">COMP. SUBCODE</td> <td style="width:15%;">VALVE SUBCODE</td> </tr> <tr> <td>E E (11)</td> <td>E (12)</td> <td>A (13)</td> <td>C K T B R K (14)</td> <td>A (15)</td> <td>Z (16)</td> </tr> <tr> <td>9 10</td> <td>11</td> <td>12</td> <td>13</td> <td>18</td> <td>20</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">LEP RO REPORT NUMBER</td> <td style="width:15%;">EVENT YEAR</td> <td style="width:15%;">SEQUENTIAL REPORT NO.</td> <td style="width:15%;">OCCURRENCE CODE</td> <td style="width:15%;">REPORT TYPE</td> <td style="width:15%;">REVISION NO.</td> </tr> <tr> <td>(17)</td> <td>7 8</td> <td>0 1 2</td> <td>0 3</td> <td>L</td> <td>0</td> </tr> <tr> <td>21</td> <td>22</td> <td>24</td> <td>26</td> <td>30</td> <td>32</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">ACTION TAKEN</td> <td style="width:15%;">FUTURE ACTION</td> <td style="width:15%;">EFFECT ON PLANT</td> <td style="width:15%;">SHUTDOWN METHOD</td> <td style="width:15%;">HOURS</td> <td style="width:15%;">ATTACHMENT SUBMITTED</td> <td style="width:15%;">NPRD-4 FORM SUB.</td> <td style="width:15%;">PRIME COMP. SUPPLIER</td> <td style="width:15%;">COMPONENT MANUFACTURER</td> </tr> <tr> <td>A (18)</td> <td>Z (19)</td> <td>Z (20)</td> <td>Z (21)</td> <td>0 0 0 0</td> <td>N (23)</td> <td>Y (24)</td> <td>A (25)</td> <td>M 1 7</td> </tr> <tr> <td>33</td> <td>34</td> <td>35</td> <td>36</td> <td>37</td> <td>40</td> <td>41</td> <td>43</td> <td>44</td> </tr> </table>																						SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE	E E (11)	E (12)	A (13)	C K T B R K (14)	A (15)	Z (16)	9 10	11	12	13	18	20	LEP RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.	(17)	7 8	0 1 2	0 3	L	0	21	22	24	26	30	32	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	A (25)	M 1 7	33	34	35	36	37	40	41	43	44
SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE																																																																															
E E (11)	E (12)	A (13)	C K T B R K (14)	A (15)	Z (16)																																																																															
9 10	11	12	13	18	20																																																																															
LEP RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.																																																																															
(17)	7 8	0 1 2	0 3	L	0																																																																															
21	22	24	26	30	32																																																																															
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER																																																																												
A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	A (25)	M 1 7																																																																												
33	34	35	36	37	40	41	43	44																																																																												
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																																																																																				
1 0		A failed trip coil caused the breaker failure. The breaker was replaced with																																																																																		
1 1		a spare and the D/G was tested and returned to service. The defective trip coil was																																																																																		
1 2		replaced and the breaker was tested satisfactorily. The trip coil failed with																																																																																		
1 3		an open circuit. This is the first occurrence of this type. No further action is																																																																																		
1 4		necessary.																																																																																		
7 8 9																																																																																				
<table border="0" style="width:100%;"> <tr> <td style="width:15%;">FACILITY STATUS</td> <td style="width:15%;">% POWER</td> <td style="width:15%;">OTHER STATUS</td> <td style="width:15%;">METHOD OF DISCOVERY</td> <td style="width:15%;">DISCOVERY DESCRIPTION</td> </tr> <tr> <td>E (28)</td> <td>1 0 0 (29)</td> <td>NA</td> <td>B (31)</td> <td>Surveillance Testing</td> </tr> <tr> <td>10</td> <td>12</td> <td>13</td> <td>44</td> <td>45</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">ACTIVITY RELEASED</td> <td style="width:15%;">CONTENT</td> <td style="width:15%;">AMOUNT OF ACTIVITY</td> <td style="width:15%;">LOCATION OF RELEASE</td> </tr> <tr> <td>Z (33)</td> <td>Z (34)</td> <td>NA</td> <td>NA</td> </tr> <tr> <td>10</td> <td>11</td> <td>44</td> <td>45</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">PERSONNEL EXPOSURES</td> <td style="width:15%;">TYPE</td> <td style="width:15%;">DESCRIPTION</td> </tr> <tr> <td>0 0 0 (37)</td> <td>Z (38)</td> <td>NA</td> </tr> <tr> <td>11</td> <td>12</td> <td>13</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">PERSONNEL INJURIES</td> <td style="width:15%;">DESCRIPTION</td> </tr> <tr> <td>0 0 0 (40)</td> <td>NA</td> </tr> <tr> <td>11</td> <td>12</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">LOSS OF OR DAMAGE TO FACILITY</td> <td style="width:15%;">DESCRIPTION</td> </tr> <tr> <td>Z (42)</td> <td>NA</td> </tr> <tr> <td>11</td> <td>12</td> </tr> </table> <table border="0" style="width:100%;"> <tr> <td style="width:15%;">PUBLICATION</td> <td style="width:15%;">DESCRIPTION</td> </tr> <tr> <td>N (44)</td> <td>NA</td> </tr> <tr> <td>11</td> <td>12</td> </tr> </table>																						FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	E (28)	1 0 0 (29)	NA	B (31)	Surveillance Testing	10	12	13	44	45	ACTIVITY RELEASED	CONTENT	AMOUNT OF ACTIVITY	LOCATION OF RELEASE	Z (33)	Z (34)	NA	NA	10	11	44	45	PERSONNEL EXPOSURES	TYPE	DESCRIPTION	0 0 0 (37)	Z (38)	NA	11	12	13	PERSONNEL INJURIES	DESCRIPTION	0 0 0 (40)	NA	11	12	LOSS OF OR DAMAGE TO FACILITY	DESCRIPTION	Z (42)	NA	11	12	PUBLICATION	DESCRIPTION	N (44)	NA	11	12									
FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION																																																																																
E (28)	1 0 0 (29)	NA	B (31)	Surveillance Testing																																																																																
10	12	13	44	45																																																																																
ACTIVITY RELEASED	CONTENT	AMOUNT OF ACTIVITY	LOCATION OF RELEASE																																																																																	
Z (33)	Z (34)	NA	NA																																																																																	
10	11	44	45																																																																																	
PERSONNEL EXPOSURES	TYPE	DESCRIPTION																																																																																		
0 0 0 (37)	Z (38)	NA																																																																																		
11	12	13																																																																																		
PERSONNEL INJURIES	DESCRIPTION																																																																																			
0 0 0 (40)	NA																																																																																			
11	12																																																																																			
LOSS OF OR DAMAGE TO FACILITY	DESCRIPTION																																																																																			
Z (42)	NA																																																																																			
11	12																																																																																			
PUBLICATION	DESCRIPTION																																																																																			
N (44)	NA																																																																																			
11	12																																																																																			
2 0																																																																																				
7 8																																																																																				
NRC USE ONLY																																																																																				
2 0																																																																																				
7 8																																																																																				

NAME OF PREPARER G. H. Ruiter

PHONE: (414) 433-1329