a: ,•	REGULATOR	Y INFORM	ATION	DIST	RIBUTION SYSTE	M (RIDS	\$)	
PACIL:50 AUTH.NA BUTTER.O	N'NBR:7907050309)=305 Kewaunee Nu AME AUTHUR S.H. Wiscons NAME RECIPI Regio	clear Po AFFILIA in Publi ENT AFFI	wer P TION c Ser LIATI	lant, vice DN	Wisconsin Pub	lic Ser	DOCKET # rvic 05000305	75
SUBJECT: LER 79-011/03L-0 on 790530:during refueling shutdown,testing indicated three of four pressurizer pressure transmitters were out of calibr.Caused by instrument drift of Foxboro pressure transmitters.Transmitters recalibr.								
DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR ENCL SIZE: TITLE: INCIDENT REPORTS								
ACTION:	RECIPIENT ID CODE/NAME 05 BC	4	4				ES ENCL	
INTERNAL :	01 REG FILE 09 I&E 14 TA/EDO 16 EEB 18 PLANT SYS BR 20 AD PLANT SYS 22 REAC SAFT BR 24 KREGER 26 AD/SITE ANAL 28 ACDENT ANLYS E JORDAN/IE TMI DOC CENTER		1 2 1 1 1 1 1 1 1 1 1 1 1	02 11 15 17 21 23 25 27 29 HAT	NRC PDR MPA NOVAK/KNIEL AD FOR ENGR I&C SYS BR AD SYS/PROJ ENGR BR PWR SYS BR OPERA LIC BR AUX SYS BR AUX SYS BR	1 3 1 1 1 1 1 1 1	1	
	03 LPDR 29 ACRS	1 16	1 16	04	NSIC	1	1	

Ì

NHC FURM 366 (7.77)LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: REPORT L 6 0 5 0 0 0 3 0 5 7 0 5 3 0 7 9 8 0 6 2 9 7 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 CON'T 0 1 During refueling shutdown, surveillance testing indicated that three of four pres-0 2 surizer pressure transmitters were out of calibration such that their high pressure 03 reactor trip settings were above the TS setpoint by at most 0.29%. This placed the 0 4 facility under reporting requirement of TS 6.9.2.b(1). Reactor trip would have oc-0 5 curred well below the limiting trip point assumed in the FSAR. The reactor was shut-0 6 down at time of discovery. There was no effect on plant operation or public safety. 0 7 80 0 8 q COMP VALVE SUBCODE SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE CODE SUBCODE CODE S | T | R | U |(14) T Z (13) X (12) 10 13 REVISION OCCURRENCE REPORT SEQUENTIAL TYPE NO. REPORT NO. EVENT YEAR LER/RO 0 | 1 | 1(17) REPORT NUMBER ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. COMPONENT ACTION FUTURE SHUTDOWN METHOD MANUFACTUREF SUPPLIER ONPLANT 0 Z_21 N (25) F 1 8 0 (26) Z 20 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Instrument drift of the Foxboro pressure transmitters caused them to be out of cali-1 0 The transmitters were recalibrated with no indication of other problems. bration. 1 1 1 No further action required. 1 21 3 4 80 B 31 Surveillance Testing METHOD OF DISCOVERY DESCRIPTION (32) OTHER STATUS FACILITY DISCOVERY % POWER 0 0 0 29 NA | H | (28) 5 80 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY 35 RELEASED_OF RELEASE NA Z 33 Z 34 NA 80 44 11 PERSONNEL EXPOSURES DESCRIPTION (39) τγρε NUMBER 0 0 0 37 Z 38 NA 7 80 11 12 PERSONNEL INJURIES DESCRIPTION (41) NUMBER (40) NA 0 8 80 12 11 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION TYPE Z (42) I NA 9 80 10 NRC USE ONLY PUBLICITY DESCRIPTION (45) 7907050309 ISSUED N (44) NA 0 80 68 69 10 (414) 433-1329 G. H. Ruiter PHONE: NAME OF PREPARER _

NRC FOR (7-77)	LICENSEE EVENT REPORT
r	CONTROL BLOCK:
$\begin{bmatrix} 0 \\ 1 \\ 7 \\ 8 \end{bmatrix}$	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
	REPORT L 6 0 5 0 0 0 3 0 5 7 0 5 3 0 7 9 8 0 6 2 9 7 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During refueling shutdown, surveillance testing indicated that three of four pres-
0 2	surizer pressure transmitters were out of calibration such that their high pressure
03	reactor trip settings were above the TS setpoint by at most 0.29%. This placed the
0 4	facility under reporting requirement of TS 6.9.2.b(1). Reactor trip would have oc-
05	
06	<u>curred well below the limiting trip point abound in the prototion or public safety.</u>
0 7	down at time of discovery. There was no effect on plant operation of public surgey.
08 78	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
09	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	$\frac{1}{33}$ $\frac{1}{34}$ $\frac{1}{35}$ $\frac{1}{36}$ $\frac{3}{36}$ $\frac{3}{37}$ $\frac{40}{41}$ $\frac{41}{42}$ $\frac{42}{43}$
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2) Instrument drift of the Foxboro pressure transmitters caused them to be out of cali-
11	bration. The transmitters were recalibrated with no indication of other problems.
12	No further action required.
13	
14 7 8	9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 STATUS % POWER OTHER STATUS 30 DISCOVERY DESCRIPTION 32
15 78	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
	NCTIVITY CONTENT LOCATION OF RELEASE 0 10 11 44 0 10 11 44
$\begin{bmatrix} 1 & 7 \\ 7 & -8 \end{bmatrix}$	0 0 0 37 Z 38 NA 80
1 8	
7 8	11 12 LOSS OF OR DAMAGE TO FACILITY (43) 7907050309 Z (42) NA 7907050309
7 8	9 9 9 10 10 10 10 10 10 10 10 10 10
7 8	9 10 9 10 NAME OF PREPARER <u>G. H. Ruiter</u> PHONE: <u>(414)</u> 433-1329