(7-77)	LICENSEE EVENT REPORT
J	· CONTROL BLOCK:
	$ \begin{array}{ c c c c c } \hline W & I & K & P & 1 \\ \hline 9 & \text{Licensee code} & 14 \\ \hline 14 & 2 & 0 \\ \hline 15 & \text{License number} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License number} \\ \hline 15 & \text{License number} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License number} \\ \hline 15 & \text{License type} \\ \hline 15 & \text{License type}$
GON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 0 5 7 0 3 0 5 8 0 8 0 4 0 1 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9
0 2	While testing 1B diesel generator operability for ICP's on 1A diesel generator, 1B
03	diesel generator failed to start. Diesel generator 1A was tested and found operable.
04	Diesel generator 1B was taken out of service, thus placing the system under 6.9.2b.2.
0 5	Since one diesel generator was verified operable and off-site power was available,
06	there was no effect on plant operation or public safety.
07	
08 78	9 SYSTEM CAUSE CAUSE CAUSE CAUSE SUBCODE
09 78	$\begin{array}{c} \begin{array}{c} \text{CODE} \\ \text{CODE} \end{array} \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \end{array} \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \end{array} \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \end{array} \\ \hline \end{array} \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \end{array} $ \\ \hline \begin{array}{c} \text{SUBCODE} \end{array} \\ \hline \end{array} \\ \hline \end{array} \\ \hline \end{array} \\ \hline \end{array}
	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
10	Primary air start motors would not rotate engine to start 1B diesel generator.
11	The air motors were removed and inspected. No obvious problems were found. The
12	motors were sent to the manufacturer for further investigation. The motors were
13	replaced by factory rebuilt motors. Further action is dependent on the results of the
$\begin{bmatrix} 1 \\ 4 \end{bmatrix}$	<u>manufacturers investigation.</u>
	FACILITY STATUS % POWER OTHER STATUS (30) DISCOVERY DISCOVERY DESCRIPTION (32) F (28) 1 0 0 (29) NA B (31) Surveillance Procedure
	9 10 12 13 13 13 14 44 45 46 LOCATION OF RELEASE ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE
1 6 7 8	$\begin{bmatrix} \underline{Z} \\ 9 \\ 10 \\ 10 \\ 11 \\ 11 \\ 44 \\ 45 \\ 80 \\ 80 \\ 80 \\ 80 \\ 80 \\ 80 \\ 80 \\ 8$
17	
7 8	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 <u>8</u> 7 8	0 0
1 9 7 8	9 10 NBC USE ONLY
2 0	
78	9 10 NAME OF PREPARER David S. Nalepka PHONE: <u>388-2560</u>