

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

May 23, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 80-021/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 80-021/03L-0 is being submitted. The requirement to report this event within thirty days was not met due to reporting requirement ambiguities; initial informal notification of Region III personnel was made within thirty days and they concurred with our opinion that the event need not be reported. Subsequent review of the event resulted in a reversal of our decision and the issue of the attached LER.

Very truly yours,

A handwritten signature in cursive script that reads "E. R. Mathews".

E. R. Mathews, Vice President
Power Supply & Engineering

snf

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, D. C. 20555
Mr. W. Lavallee, NSAC
P O Box 10412, Palo Alto, CA 94303

Handwritten initials: "A002 5/11"

8005290 416

1944

THE UNITED STATES OF AMERICA

IN SENATE
JANUARY 10, 1944

REPORT

OF THE
COMMISSION ON THE ORGANIZATION
OF THE EXECUTIVE BRANCH

Submitted to the Senate and House of Representatives
in accordance with the provisions of the Executive Order
of the President of the United States, dated August 1, 1943,
and the Senate Resolution of July 1, 1943, and the House
Resolution of July 1, 1943, both relating to the
organization of the Executive Branch of the Government.

WASHINGTON

GOVERNMENT PRINTING OFFICE

1944

For sale by the Government Printing Office
at the rate of \$1.00 per copy plus postage
and handling charges. Single copies of this
report may be obtained from the Superintendent
of Documents, Government Printing Office,
Washington, D. C.

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

May 23, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 80-021/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 80-021/03L-0 is being submitted. The requirement to report this event within thirty days was not met due to reporting requirement ambiguities; initial informal notification of Region III personnel was made within thirty days and they concurred with our opinion that the event need not be reported. Subsequent review of the event resulted in a reversal of our decision and the issue of the attached LER.

Very truly yours,

E. R. Mathews, Vice President
Power Supply & Engineering

snf

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, D. C. 20555
Mr. W. Lavalley, NSAC
P O Box 10412, Palo Alto, CA 94303

A002
5/11
MAY 28 1980

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

017 | WIKNP12 | 00-000000-003 | 411114 | 5

CON'T
 REPORT SOURCE L6 | 050003057 | 0328808 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | The monthly vibration test required by the Inservice Inspection Program was not per-

03 | formed within the required time interval on one component cooling pump (IWP-3400(a),

04 | ASME section XI). Since the component cooling pumps are alternately placed in service

05 | during normal plant operation the pump had been operated during the test interval;

06 | this event had no effect on plant operation or public safety.

07 |

08 |

SYSTEM CODE WB11 | CAUSE CODE A12 | CAUSE SUBCODE C13 | COMPONENT CODE PUMPXX14 | COMP. SUBCODE B15 | VALVE SUBCODE Z16

LER/RO REPORT NUMBER 8017 | EVENT YEAR 802122 | SEQUENTIAL REPORT NO. 02123242526 | OCCURRENCE CODE 03272829 | REPORT TYPE L3031 | REVISION NO. 032

ACTION TAKEN H1833 | FUTURE ACTION H1934 | EFFECT ON PLANT Z2035 | SHUTDOWN METHOD Z2136 | HOURS 000022373839 | ATTACHMENT SUBMITTED N234041 | NPRD-4 FORM SUB. N2442 | PRIME COMP. SUPPLIER Z2543 | COMPONENT MANUFACTURER Z9992644454647

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The performance of the monthly vibration test is normally coordinated with routine

11 | operation of the pump as allowed by IWP-3400(b). The vibration measurements were made

12 | 3 days beyond the allowable grace period. Continued awareness of ISI requirements

13 | will minimize recurrence of this event.

14 |

FACILITY STATUS E28 | % POWER 10029 | OTHER STATUS NA30 | METHOD OF DISCOVERY B31 | DISCOVERY DESCRIPTION Administrative Review.32

ACTIVITY CONTENT Z33 | RELEASED OF RELEASE Z34 | AMOUNT OF ACTIVITY NA35 | LOCATION OF RELEASE NA36

PERSONNEL EXPOSURES NUMBER 00037 | TYPE Z38 | DESCRIPTION NA39

PERSONNEL INJURIES NUMBER 00040 | DESCRIPTION NA41

LOSS OF OR DAMAGE TO FACILITY TYPE Z42 | DESCRIPTION NA43

PUBLICITY ISSUED N44 | DESCRIPTION NA45

NAME OF PREPARER John Wallace

NRC USE ONLY

PHONE: (414) 433-1329