REGULATION INFORMATION DISTRIBUTION STEM (RIDS)

ACCESSION NBR: 8707090187 DOC. DATE: 87/07/03 NOTARIZED: NO DOCKET # FACIL: 50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305 AUTH. NAME AUTHOR AFFILIATION HINTZ, D. C. Wisconsin Public Service Corp. RECIP. NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Summary Technical Rept on Type A,B & C Leak Rate Test Performed at Kewaunee Nuclear Power Plant from 1985 to 1987," per 10CFR50, App J. Rept provides results from Type A test performed on reeactor containment bldg.

DISTRIBUTION CODE: A017D COPIES RECEIVED:LTR _/ ENCL __ SIZE: ______SIZE: ______SIZE: ______SIZE: ______SIZE: _____SIZE: ______SIZE:

NOTES: SEE RA

	RECIPIENT ID CODE/NAME PD3-3 LA QUAY,T	COPII LTTR 1 1		RECIPIENT ID CODE/NAME PD3-3 PD		IES ENCL 5
INTERNAL:	ARM/DAF/LFMB DGC/HDS1 RES DEPY GI RES/DE/EIB RES/DRAA/SAIB	1 1 1 1	O 1 1 1 1	NRR/DEST/PSB REG FILE 01 RES TELFORD, J RES/DE/SSEB RES/DRPS/RPSIB	1 1 1 1	1 1 1 1
EXTERNAL:	LPDR NSIC	1 1	1 1	NRC PDR	1	1



WISCONSIN PUBLIC SERVICE CORPORATION

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

July 3, 1987

10 CFR 50, Appendix J

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Gentlemen:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Reactor Containment Building Integrated Leak Rate Test

In accordance with the requirements of 10 CFR 50, Appendix J, V.B.3, this letter submits the summary technical report on the results of Type A, B, and C leak rate tests performed at the Kewaunee Nuclear Power Plant (KNPP). The report provides the results from the Type A test performed on the KNPP reactor containment building during the 1987 refueling outage and the results from the Type B and C local leak rate tests performed since the previous Type A test of 1984. The as-left results of the Type A, B, and C tests were within the acceptance criteria of 10 CFR 50, Appendix J.

Also, included as an accompanying report is an analysis of excessive leakage found in electrical penetration 34-E during the 1985 refueling outage. The as-found leak rate of the penetration was greater than the range of the leak rate measuring equipment and could not be quantified. The analysis describes the configuration of the penetration, the reason for the excessive leakage, corrective actions taken, and why the excessive leak rate did not exceed the acceptance criteria of 10 CFR 50, Appendix J for Type B and C tests in 1985.

If you have any questions regarding the enclosed reports, feel free to contact my staff.

PDR

8707090187 870703

ADOCK 05000305

Sinder

D. C. Hinťz Vice President – Nuclear Power

PDR

PIS/jms Enc. cc - Mr. Robert Nelson, US NRC US NRC, Region III