

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

Р

R

R

D

M

ACCESSION NBR:9512180131 DOC.DATE: 95/12/14 NOTARIZED: NO DOCKET # FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305 AUTH.NAME AUTHOR AFFILIATION MARCHI,M.L. Wisconsin Public Service Corp. RECIP.NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)								
SUBJECT: Forwards LER 95-007-00. Submittal delayed as discussed w/NRC. Suppl rept will be submitted following completion of investigation of event & long term corrective actions to resolve AFW pump lubricating oil level fluctuations.								
DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR _ ENCL _ SIZE: 1+18 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.								
NOTES:								
	RECIPIENT ID CODE/NAME PD3-3 PD	COPIE LTTR 1			PIENT DDE/NAME R	COPI LTTR 1		
INTERNAL:	ACRS AEOD/SPD/RRAB NRR/DE/ECGB NRR/DE/EMEB NRR/DRCH/HICB NRR/DRCH/HQMB NRR/DSSA/SPLB RES/DSIR/EIB	1 1 1 1 1 1 1	1 1 1 1 1 1 1	AEOD/SF FILE CE NRR/DE/ NRR/DRC NRR/DRC NRR/DRF NRR/DSS RGN3	EELB CH/HHFB CH/HOLB CM/PECB	2 1 1 1 1 1 1	2 1 1 1 1 1 1	
EXTERNAL:	L ST LOBBY WARD NOAC MURPHY,G.A NRC PDR	1 1 1	1 1 1	NOAC PO	RYCE,J H ORE,W. FULL TXT	2 1 1	2 1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083.) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 26

WISCONSIN PUBLIC SERVICE CORPORATION

600 North Adams • P.O. 8ox 19002 • Green Bay, WI 54307-9002

December 14, 1995

10 CFR 50.73

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Ladies/Gentlemen:

Docket 50-305
Operating License DPR-43
Kewaunee Nuclear Power Plant
Reportable Occurrence 95-007-00

In accordance with the requirements of 10 CFR 50.73, "Licensee Event Report System," the attached Licensee Event Report (LER) for reportable occurrence 95-007-00 is being submitted. This submittal has been delayed as discussed with NRC Region III management.

WPSC recognizes that part of the significance of this event is that some of the resultant actions taken could have affected redundant safety related equipment. As a result, work control practices are being reviewed to identify changes which will reduce the likelihood of future events of this type. This event identified that additional management attention is needed in the way work is being prioritized, scheduled, performed and documented. The small oil level fluctuations described in this licensee event report appeared to be insignificant, but the lack of a resolution allowed the condition to linger, eventually allowing the conditions which created this event. Additionally, work control measures, including work requests and procedural guidance, need to be addressed to improve performance, retest, and documentation of work.

As noted in the LER, a supplemental report will be submitted. This will occur following the completion of our investigation of this event and long term corrective actions to resolve the auxiliary feedwater pump lubricating oil level fluctuations.

Sincerely,

M. L. Marchi

mo marches

Manager - Nuclear Business Group

MEA

Attach.

cc - INPO Records Center

US NRC Senior Resident Inspector

US NRC, Region III

Iეეეე

9512180131 951214 PDR ADDCK 05000305 Kegg.