

| MEMO ROUTE SLIP<br>Form AEC-93 (Rev. May 14, 1947) AECM 0240   |  | See me about this.  | For concurrence. | For action.      |
|--|--|---|------------------|------------------|
|  |  | Note and return.  | For signature.   | For information. |
| TO (Name and unit)<br>RO Chief, FS&EB<br>RO:HQ (4)<br>Licensing (4)<br><u>DR Central Files</u><br>Region I | INITIALS   | REMARKS<br>Iowa Electric Light & Power Company<br>Duane Arnold 50-331 |                  |                  |
|  | DATE   |   |                  |                  |
| TO (Name and unit)<br>Region II<br>PDR<br>Local PDR<br>NSIC<br>TIC   | INITIALS   | REMARKS   |                  |                  |
|  | DATE   |   |                  |                  |
| TO (Name and unit)<br>OGC, Beth, P-506A<br>F. Rizzo, RO:HQ<br>A/D for Info<br>Processing, OOE              | INITIALS   | REMARKS   |                  |                  |
|  | DATE   |   |                  |                  |
| FROM (Name and unit)<br>G. Fiorelli<br>RO:III  | REMARKS<br>Attached is licensee's reply dated November 14, 1974 to RO<br>Bulletin 74-12. |   |                  |                  |
|  |  |   |                  |                  |
| PHONE NO.  | DATE<br>11-19-74   |   |                  |                  |

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469

-5

# IOWA ELECTRIC LIGHT AND POWER COMPANY

*General Office*

CEDAR RAPIDS, IOWA

November 14, 1974

IE-74-2160

CHARLES W. SANDFORD  
EXECUTIVE VICE PRESIDENT

Docket 50-331

Mr. J. G. Keppler  
U.S. Atomic Energy Commission  
Directorate of Regulatory Operations  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Re: Duane Arnold Energy Center #1  
Subject: RO Bulletin No. 74-12 "Incorrect  
Coils in Westinghouse Type SG Relays"  
File: Q-313, A-110

Dear Mr. Keppler:

This is in reply to your letter of October 25, 1974 regarding the possibility of incorrect coil in Westinghouse Type SG Relays associated with Class IE equipment.

A thorough investigation of all electrical equipment in DAEC identified one Westinghouse Type SG Relay. This relay is not associated with Class IE equipment. The coils' resistance was checked and found to be proper for its application.

Very truly yours,

*Charles W. Sandford*  
Charles W. Sandford  
Executive Vice President

CWS/ms

cc: J. A. Wallace  
G. G. Hunt  
L. D. Root  
H. W. Rehrauer  
J. N. Ward  
G. A. Cook  
J. R. Newman

NOV 18 1974