NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM).

CONTROL NO:_

- 4647

FILE: INCIDENT REPORT FILE

•		•	FI	LE: INCID	ENT REPORT FII
FROM: Iowa Electric & Pwr Co Cedar Rapids, Io.		DATE REC'D	LTR TW	X RPT	OTHER
G.G. Hunt	4-23-75 ORIG	4-28-75 CC OTHER	XX I	L \EC PDR_	
TO:	NONE,	COOTHER	1 .		
James G. Keppler			SENT	OCAL PD	R XXX
CLASS UNCLASS PROPINFO	TUPUT	NO CYS REC'D	DOCKE	ET NO:	50-331
DESCRIPTION:		ENCLOSURES:	<u> </u>		
Ltr. trans the following	•	<u> </u>	11. 75	22 /	10: 75
trans the fortowing					19-75, concerr volume
					WIN THE
	•	·	J		
•			-		
PLANT NAME: Duane Arnold					الماليان
	FOR ACTION/	I	[· X++ · '		VCR 4-29-75
BUTLER (L) SCHWENC			J (F)		
W/ Copies W/ Copie					•
CLARK (L) STOLZ (L)) LEAR	L)		
W/ Copies W/ Copie			opies		• .
FARR (L) VASSALLO				. •	
W/ Copies W/ Copie			opies	• .	
KNIEL (L) PURPLE (L W/ Copies W/ Copie			nnies		
W/ Copies W/ Copie		DISTRIBUTION			
STOLL OF			C-F	A/T I	NID
NEGFILE TECH REV NEGFOR SCHROED		LIC AS R. DIGGS			TMAN
OGC, ROOM P-506A MACCARY		H, GEARI			ZMAN
SOSSICK/STAFF KNIGHT	KASTNER		OURNE (L)		
CASE PAWLICKI	BALLARD	P. KREUT	ZER (E)		
STAMBUSSO SHAO	SPANGLEF	J. LEE (L)	PLAN	
BOYD **> STELLO	EVIVIDO	M. MAIGR			ONALD PMAN
MOORE (L) ** HOUSTON DEYOUNG (L) ** NOVAK	<u>ENVIRO</u> MULLER	S. REED (M. SERVIO			E (Ltr)
SKOVHOLT (L) ROSS	DICKER	S, SHEPP		E. CC	
SOLLER (L) (Ltr) SIPPOLITO	KNIGHTON			PETE	ERSON
P. COLLINS &TEDESCO	YOUNGBL				TFIELD (2)
DENISE LONG	REGAN	S. TEETS		₩ KLE(
REG OPR LAINAS	PROJECT I	***	_		NHUT SINTON
FILE & REGION (2) BENAROY MIPC/PE (3) VOLLMER		V. WILSO			
, ^{mlpc/pe} (3) ,vollmer Steele .	חאוועבטט	R. INGRA	iVi (L)		AILLIAMS
31 C. L. L	EVERNIALE	MCTOIDLICION		esero HAN	IA T
-1 LOCAL DDD Cedar Rapid		ISTRIBUTION			KOW V
		v D.C	4 Dr	DR-SAN/L/	V/NI
1 - TIC (ABERNATHY) (1)(2)(10) - MATIONAL LA	ABS			EN NAT LAB
-1 NSIC (BUCHANAN) 1 ASLB	1 - W. PENNINGT1 - CONSULTANT			ULRIKSO	
1 - ASLB 1 - Newton Anderson		IS LUME/AGBABIAN			TH GUSSMAN)
-A- ACRS SENT TO LIC ASST	14 G 11 W 7 T 1 1 1 1 7 1 0 1	COMETACIONOTAL	P	lm B-127 G	Τ.
** SEND ONLY TEN DAY REPORTS	3				LES, Rm E-201
we will see model to the country of the coun		•	G	T	

IOWA ELECTRIC LIGHT AND POWER COMPAN

General Office

CEDAR RAPIDS IOWA DUANE ARNOLD ENERGY CENTERS PALO, IOWA APRIL 23, 1975 DAEC-75-173

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. A.O. 50-331/75-22

FILE: A-110

A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.

Mr. R. Knopp, of your office, was notified of the abnormal occurrence by telephone on April 19, 1975

Very truly yours,

G. G. Hunt

Chief Engineer

Duane Arnold Energy Center

DLW:GGH:bh Enclosure

CC: B. C. Rusche

C. W. Sandford

J. A. Wallace

H. W. Rehrauer-Chairman, Safety Committee

J. R. Newman

E. L. Hammond

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office CEDAR RAPIDS, IOWA

Subject:

Abnormal Occurrence

Report Number:

A.O. 50-331/75-22

Report Date:

April 23, 1975

Occurrence Date:

April 19, 1975

Facility:

Duane Arnold Energy Center, Unit #1, Palo, Iowa

Identification of Occurrence

Suppression chamber water volume, reportable in accordance with Appendix A to DPR-49, Specifications 1.0.4.b and 3.7.A.l.d.

Conditions Prior to Occurrence

Scheduled reactor power reduction from 734 MWt to 506 MWt in progress.

Description of Occurrence

Operating personnel were preparing to perform a special test on the HPCI Subsystem to verify HPCI pump flow capabilities (See Abnormal Occurrence Report No. 50-331/75-21). The test involved taking HPCI pump suction from one condensate storage tank (CST) and discharging to the other. While draining one CST to the suppression chamber in preparation for the test, suppression chamber water volume reached 65,200 cubic feet. The Technical Specification limit for maximum suppression chamber water volume is 61,500 cubic feet.

Designation of Apparent Cause of Occurrence

The cause of the occurrence was operator error. Although suppression chamber water level was being observed on a level recorder, operating personnel incorrectly read the scale on the recorder.

Analysis of Occurrence

The occurrence did not present an unsafe plant condition. The suppression chamber water volume had been in excess of Technical Specification limits approximately one hour when the error was discovered and corrective action initiated.

Corrective Action

The suppression chamber water volume was returned to Technical Specification limits.

Appropriate operating procedures will be revised to clarify the proper method of reading the scale on the suppression chamber water level recorder.

A design change request to provide an alarm on suppression chamber water level had already been initiated at the time of the occurrence. When the design change is completed, the alarm will alert operating personnel when the suppression chamber water level is approaching Technical Specification limits.

Conclusion

The DAEC Operations Committee reviewed this report on April 23, 1975. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

G. G. Hunt Chief Engineer

Duane Arnold Energy Center

DLW:GGH:bh