NRC FORM 195 (2-76)		U.S. NU	CLEAR REGULATORY COMMISSION	50.331
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL				FILE NUMBER ÎNCIDENT REPORT
O: Mr. James G. Keppl	er	Cedar	Elect. Light & Pwr Co. Rapids, Iowa 52406	DATE OF DOCUMENT 09/22/77 DATE RECEIVED
•		Ellery	L. Hammond	10/11/77
]LETTER NOTO	RIZED ASSIFIED	PROP	INPUT FORM	NUMBER OF COPIES RECEIVED
ESCRIPTION			ENCLOSURE	
	·		32) on 04/13/77 concer main and one thrust be on journal and thrust	vent Report (RO 50-331/7 ming one lower cranksha earing were found "wiped surfaces during annual diesel generator 1G31
,		1 ŗ	1p	
PLANT NAME: DUANE AR jcm 10/1				
·				
				EXPOSURE IS INVOLVED Y TO KREGER/J. COLLINS
	,	FOR ACTION/	INFORMATION	
BRANCH CHIEF:	LEAR			
W/ 3 CYS FOR ACTION				
LTC ASST.:	PARRI	HZ		
		INTERNAL	I I DISTRIBUTION	
RECEIPTLE				
NRC PDR				
I & E (2)	<u> </u>			
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON			 	
NOVAK/CHECK	 			
GRIMES				
KNIGHT RUTLER				
HANAUER				
TEDESCO		· · · · · · · · · · · · · · · · · · ·		
FISENHIT				
BAER				
SHAO				
VOLLMER/BUNCH				
KREGER/ J. COLLINS				
ROSA				
	EVTERNAL	DISTRIBUTION		CONTROL NUMBER
LPDR: CEDAR RAT		NOT DOIN ICIO	T T	CONTROL NOWIBER
1	1,32 TH	 	 	Ao
TIC:	 			
NSIC: ACRS (16) SENT AS (AT B			772850081
AURO (10) SERT AS C	T-1-			1 `
 			 	-, ₽

NRC FORM 195 (2-76)

D. Lankam

Iowa Electric Light and Power Company

DUANE ARNOLD ENERGY CENTER
P. O. Box 351

Cedar Rapids, Iowa 52406

September 22, 1977 DAEC -77 - 485

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission-Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. Update RO 77-32

(14 day)

Previous Report Date 042777

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Chief Engineer

Duane Arnold Energy Center

ELH/DLW/mg

Docket 50-331

attachment

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

Director, Management Information and Program Control (3) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

772850081

LICENSEE EVENT REPORT

	042717	
	CONTROL BLOCK: [] [PLEASE PRINT ALL REQUIRED INFORMAT	10N)
•	LICENSEE LICENSE EVENT NAME LICENSE NUMBER TYPE TYPE	
01	I A D A C 1 D O O O O O O O O O	
01 7 B	CONT CATEGORY REPORT REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE CONT TYPE SOURCE DOCKET NUMBER EVENT DATE STORY SOURCE	7 B0
	EVENT DESCRIPTION	
7 B	<u>During annual inspection of standby diesel generator 1G31, one lower cr</u>	
03 7 8	ankshaft main and one thrust bearing were found "wiped" on journal and	80
04	thrust surfaces. Bearings were replaced and engine to generator was re	
7 B	aligned. Standby diesel was tested and returned to service. Alignment	BO
7 8 06	to be checked during 1978 refuel and after approximately 100 hours ope	80
7 B	SYSTEM CAUSE COMPONENT CODE COMPONENT COMPONENT COMPONENT SUPPLIER MANUFACTURER VIOLATION E F F F E N G I N E A C 4 7 0 N 9 10 11 12 17 43 44 47 48	80
08	CAUSE DESCRIPTION [Improper alignment of engine to generator causing overload to bearings.	1
7. 6	9	80
09 7 8	Generator alignment to engine was high.	80
10 7 8		80
	FACILITY STATUS % PDWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION H 0 0 0 0	
	FORM OF ACTIVITY CONTENT	80
12	RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE NA NA	
78	9 10 11 44 45 PERSONNEL EXPOSURES	80
13	NUMBER TYPE DESCRIPTION OOO Z NA	1
7 8 9	9 11 12 13 PERSONNEL INJURIES	80
14	NUMBER DESCRIPTION NA NA	1
7 8 9		 80
15	OFFSITE CONSEQUENCES NA	
7 8 9	OSS OR DAMAGE TO FACILITY	80
	TYPE DESCRIPTION	
16 7 8 9	Z NA	80
ात्त्व । तित्व	PUBLICITY NA	
7 8 9		80
	ADDITIONAL FACTORS	
18 [' 8 9	Event Desc. Cont ration. (RO 77-32)	
기리 I		80
, 88 Lal [·	80
	NAME: D. Wilson PHONE 319-851-5611	