REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS).

ACCESSION NBR:8005280705 DOC.DATE: 80/05/19 NDTARIZED: NO DOCKET # FACIL:50=331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 AUTH.NAME AUTHOR AFFILIATION MINECK.D.L. Iowa Electric Light & Power Co. RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: R0:on 800519, during weekly maint insp,oil drain petcock was found slightly open.No oil level was indicated on governor sight glass.Petcock was fully closed.One-half pint of oil added yo governor to restore normal level to sight glass.

1

DISTRIBUTION CODE: MOOTS COPIES RECEIVED:LTR LENCL DESTRIBUTION COPIES RECEIVE

NOTES:	म्बल संबद्ध के स्ट्रेन संबद्ध मंत्राव प्रावेश प्रावेश संवत देवील त्यान संवत संवत संवत संवत संवत संवत भूल भूत	त सेवल स्वरू भाषा रहेता राजा काम स्वरू स्वरू राजा राजा स्वरू स	متابه کنده زوران هواه خان دریان جمله تراین وری وری وری در این وری بایی بایی بایی بایی بایی بایی بایی با	ne-wan dan dala tela salar dan tela dala dala dala dala silar dala dala dala telah si	يون خرار بين مريد مريد هو
·	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
INTERNAL:	BERLINGER, C.	1 2 1 1	02 NRC PDR AEOD Hanauer,s.	1 1 1	
EXTERNAL:	03 LPDR	1	NSIC	1	

MAY 29 1980

## Iowa Electric Light and Power Company

May 19, 1980 DAEC - 80 - 237

Mr. James G. Keppler, Director Office of Inspection and Enforcement - Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

MAY 23 1380

## Subject: Prompt Notification of a Reportable Occurrence

## File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated:

Description Occurrence: During a weekly maintenance inspection, the oil drain petcock on the governor for standby diesel generator IG-31 was found open slightly and no oil level was indicated on the governor sight glass. The petcock was closed fully and approximately one half pint of oil was added to the governor to restore normal level to the sight glass. Additional corrective actions are being reviewed.

Very truly yours,

Daniel L. Mineck Chief Engineer Duane Arnold Energy Center

DLM/JVS/n

cc: Director, Management Information and Program Control (2)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8005280705

Duane Arnold Energy Center • P.O. Box 351 • Cedar Rapids, Iowa 52406 • 319/851-5611