REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:	7903270457 DOC.DATE: 79/03/21 NOTARIZED: NO	DOCKET #
	DUANE ARNOLD ENERGY CENTER, IOWA ELECTRIC LIGHT & POW	N 05000331
AUTH NAME	AUTHOR AFFILIATION	5 A
HAMMOND, E.L.	IOWA ELECTRIC LIGHT & POWER CO.	
RECIP, NAME	RECIPIENT AFFILIATION	
KEPPLER, J.G.	REGION 3, CHICAGO, OFFICE OF THE DIRECTOR	

SUBJECT: DURING SURVEILLANCE TESTING ON 790321, BOTH EMERGENCY SVC WATER SYS BECAME INOPERABLE DUE TO STRAINER PLUGGING ACTION INITIATED IMMEDIATELY TO CLEAN STRAINERS, BOTH SYS WERE: OPERABLE WITHIN 2.5=H.

DISTRIBUTION CODE: A0025 COPIES RECEIVED:LTR / ENCLE 9 SIZE: Market Bornet TITLE: INCIDENT REPORTS

NOTES	and and the second s Second second		n an	
	RECIPIENT	COPIES	RECIPIENT	COPIES
	ID CODE/NAME	LTTR ENCL	ID CODE/NAME	LTTR ENCL
ACTION:	05 BC ORB #3	4		
INTERNAL	OR REG FILE	1	02 NRC DR	1
	09 ISE	2	11 MPA	3
	14 TAZEDO	1	15 NOVAK/KNIEL:	4 1 / 19 / 19
	16 EEB	- 1	17 AD FOR ENGR	1
	18 PLANT SYS BR	1	19 18C SYS BR	
	20 AD PLANT SYS	1	21 AD SYS/PROJ	1
	22 REAC SAFT BR	1	23 ENGR BR	1
	24 KREGER	1	25 PWR SYS BR	1
	26 AD/SITE ANAL	1	27 OPERA LIC BR	ī
	28 ACDENT ANLYS	1	29 AUX SYS BR	ī
	E JORDAN/IE	· 1 ·		
EXTERNAL	03 LPDR	1	04 NSIC	1
	29 ACRS	16 🕌	,	-

MAR 28 1979

MA 4

÷ .

1.1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 FNC

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER P. O. Box 351 Cedar Rapids, Iowa 52406 March 21, 1979 DAEC - 79 - 57

Mr. James G. Keppler, Director Office of Inspection and Enforcement-Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> Subject: Prompt Notification of a Reportable Occurrence

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated: 3.8.C.1.

Description Occurrence: During surveillance testing on 3-21-79, both emergency service water systems became inoperable due to strainer plugging. Action was immediately initiated to clean the strainers. Both emergency service water systems were again operable within 2.5 hours and plant shutdown was not necessary.

Very truly yours,

Ellere L.

Ellery L. Hammond Chief Engineer Duane Arnold Energy Center

ELH/JVS/nf

Director, Management Information and Program Control (2) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

7903270457