| | REGULATEY INFORMATION DISTRIBUTIO SYSTEM (RIDS) |
|--------------------------|--|
| ACCESSION N | BR:8210260489 DUC.DATE: 82/10/15 NOTARIZED: NO DOCKET # |
| | 31 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 |
| MINECK, D.L RECIP.NAM | |
| DENTON, H.R | • Office of Nuclear Reactor Regulation, Director |
| 1 | orwards for review "MSIV Local Leak Rate Testing," per QCFR50,App J & Reg Guide 10.1. |
| DISTRIBUTI TITLE: OR | UN CODE: A001S COPIES RECEIVED:LTRENCL _/ SIZE:93 Submittal: General Distribution |
| NOTES: | |

| | RECIPIENT | | COPIES | | RECIPIEN | COPIES | | |
|----------------|-------------|------|--------|------|------------|------------|------|-------|
| | ID CODE/NAM | E | LTTR | ENCL | ID CODE/N | AME | LTTR | ENCL |
| | NRR ORB2 BC | 01 * | 7 | 7 | | | | |
| INTERNAL: | ELD/HDS2 | | 1. | 0 | NRR/DHFS D | EPY08 | 1 | 1 |
| | NRR/DL DIR | | 1 - | 1 | NRR/DL/ORA | B . | .1 | Ŭ . |
| , | NRR/DSI/RAB | | 1 | 1 | REG FILE | 04 | 1 | 1 |
| | RGN3 | | 1 | 1 | | | | |
| | | , | , | . J. | | | • | • • • |
| EXTERNAL: | ACRS | 09 | 6 | 6 | LPDR | 03 | - 1 | 1 |
| х ^с | NRC PDR | 02: | 1 | 1 | NSIC | 0.5 | 1 1 | 1. |
| | NTIS | | 1 | 1 | | | • | |

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 22

Iowa Electric Light and Power Company October 15, 1982 DAEC-82-752

Mr. Harold Denton, Director Office of Nuclear Reactor Regulatiopn U. S. Nuclear Regulatory Commission 1717 H. Street N.W. Washington, D. C. 20545

Re: Duane Arnold Energy Center

Subject: Unique Report 82-02, Main Steam Isolation Valves (MSIV) Type C Local Leak Rate Tests (LLRT)

Reference: Ltr DAEC-82-437, Mineck to Keppler, "Licensee Event Report No. 82-034 (14 day)," dated June 16, 1982.

File: A-118, NRC-1

Dear Mr. Keppler:

This letter transmits twelve copies of the MSIV Type C LLRT report for your review and information in accordance with 10CFR 50, Appendix J and Regulatory Guide 10.1. The four inboard MSIVs were leak rate tested as part of the corrective action committed-to in Licensee Event Report (LER) 82-034, see Reference. This LER describes the June 2, 1982, reportable occurrence involving the event that damaged two inboard MSIVs. Subsequently, the four inboard MSIV actuators were rebuilt, inspected and leak rate tested. The LLRT report is attached.

If there are any questions, please feel free to contact me.

Very truly yours,

Moner

Daniel L. Mineck Plant Superintendent - Nuclear

DLM/SLB/pf*

Docket No. 50-0331

8210260489 821015 PDR ADOCK 05000331

Attachment: MSIV LLRT Report

PDR