

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9007240103 DOC.DATE: 90/07/17 NOTARIZED: YES DOCKET #
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH.NAME AUTHOR AFFILIATION
 MINECK,D.L. Iowa Electric Light & Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411)

SUBJECT: Responds to NRC Bulletin 90-001, "Loss of Fill Oil in Transmitter Mfg by Rosemount."

DISTRIBUTION CODE: IE39D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2
 TITLE: NRC Bulletin 90-001, Loss of Fill Oil in Transmitters Mfg by Rosemount

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-3 LA		1	0		PD3-3 PD		1	1
	HALL,J.R.		1	1					
INTERNAL:	NRR LE,N		1	1		NRR PERCH,R		1	1
	NRR RAMSEY,J		2	2		NRR/DRIS/RVIB		1	1
	<u>REG FILE</u> 02		1	1		RES FARMER,W		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13-0

Iowa Electric Light and Power Company

July 17, 1990

NG-90-1625

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

Subject: Duane Arnold Energy Center
Docket No: 50-331
Op. License No: DPR-49
NRC Bulletin No. 90-01, "Loss of Fill-Oil in
Transmitters Manufactured by Rosemount"
File: A-101a, C-61

Dear Dr. Murley:

NRC Bulletin 90-01, "Loss of Fill-Oil in Transmitters Manufactured by Rosemount," requests licensees to take specified actions in connection with certain pressure and differential pressure transmitters.

Rosemount pressure and differential pressure transmitter models 1153B and D and 1154 appear to be susceptible to failure due to a loss of fill-oil. The Bulletin requests that licensees identify any of these models installed and take several actions to preclude this failure in service.

We have determined that we have no Rosemount model 1153B or D or 1154 pressure or differential pressure transmitters installed in either safety or ATWS-related applications at Duane Arnold Energy Center. No other action need be taken under the Bulletin. We also reviewed the performance of the Rosemount models 1151, 1152 and 1153 installed at DAEC and concluded that none has exhibited symptoms indicative of a loss of fill-oil or has been confirmed to have experienced a loss of fill-oil.

As requested in the Bulletin, we will notify you of any further developments regarding this matter should they arise.


9007240103 900717
PDR ADOCK 05000381
Q PDC

IE 39
1/0


Dr. Thomas E. Murley
July 17, 1990
NG-90-1625
Page 2

This letter is true and accurate to the best of my knowledge and belief.

IOWA ELECTRIC LIGHT AND POWER COMPANY

By 
DANIEL L. MINECK
Manager, Nuclear Division

Subscribed and sworn to before me on
this 18th day of July,
1990.


Notary Public in and for the State
of Iowa

DLM/SRC/pjv+

cc: S. Catron
L. Liu
L. Root
D. Mineck
J. R. Hall (NRC-NRR)
A. Bert Davis (Region III)
NRC Resident Office
Commitment Control Nos. 900062, 900063