

Appendix A

NOTICE OF VIOLATION

Iowa Electric Light and Power Company

Docket No. 50-331

As a result of the inspection conducted on September 1-2, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10 CFR 50, Appendix B, Criterion V states in part that "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings.

DAEC Quality Directive No. 1306.1, Revision 1, "Document Control," states in part that "those participating in an activity shall be made aware of and use proper and current instruction, procedures, and drawings ..." and that "...all documents shall be controlled as necessary to preclude the use of outdated or inappropriate documents.

Contrary to the above, an outdated copy of Surveillance Test Procedure No. 43D001 was used on July 7, 1981 to determine the reactivity anomaly for Cycle 6 after one effective full power month of operation.

This is a Severity Level VI violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

SEP 28 1981

Dated _____

"Original Signed by C.E. Norelius"

C. E. Norelius, Director
Division of Engineering and
Technical Inspection

8110080434 810928
PDR ADDCK 05000331
Q PDR