

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9107030039      DOC.DATE: 91/06/24      NOTARIZED: NO      DOCKET #  
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow      05000331  
 AUTH.NAME      AUTHOR AFFILIATION  
 MINECK, D.L.      Iowa Electric Light & Power Co.  
 RECIPIENT NAME      RECIPIENT AFFILIATION  
 MURLEY, T.E.      Office of Nuclear Reactor Regulation, Director (Post 870411 R

SUBJECT: Confirms commitment for trending, insp, repair & root cause analysis of MSIV CV-4419, per NRC 910524 temporary waiver of compliance from TS 4.7.D.1.c. Root cause analysis problem will be performed prior to Cycle 12 startup. I  
 D

DISTRIBUTION CODE: A001D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 2 S  
 TITLE: OR Submittal: General Distribution /

NOTES:

	RECIPIENT		COPIES		
	ID CODE/NAME	LTTR	ENCL		
	PD3-3 LA	1	1		
	HALL, J.R.	2	2		
INTERNAL:	ACRS	6	6	NRR/DET/ECMB 7D	1 1
	NRR/DET/ESGB	1	1	NRR/DOEA/OTSB11	1 1
	NRR/DST 8E2	1	1	NRR/DST/SELB 7E	1 1
	NRR/DST/SICB8H7	1	1	NRR/DST/SRXB 8E	1 1
	NUDOCS-ABSTRACT	1	1	OC/LFMB	1 0
	OGC/HDS2	1	0	<del>REG-FILE</del> 01	1 1
	RES/DSIR/EIB	1	1		
EXTERNAL:	NRC PDR	1	1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 24 ENCL 22

*m/A-f*  
*ent*

R  
I  
D  
S  
/  
A  
D  
D  
S

Iowa Electric Light and Power Company

June 24, 1991

NG-91-1594

Dr. Thomas E. Murley, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

Subject: Duane Arnold Energy Center  
Docket No: 50-331  
Op. License No: DPR-49  
Commitment for the Trending, Inspection, Repair, and  
Root Cause Analysis of Main Steam Isolation Valve  
CV-4419

Reference: Letter, D. L. Mineck (Iowa Electric) to Dr. T.E. Murley  
(NRC) dated December 14, 1990., NG-90-2839

File: A-117, N-11

Dear Dr. Murley:

On May 24, 1991 we received a Temporary Waiver of Compliance (TWOC) from the DAEC Technical Specification (TS 4.7.D.1.c) requirement to exercise the Main Steam Isolation Valves (MSIVs) at least once per week by partial closure. The Waiver became necessary to avoid potential further damage to one MSIV (CV-4419) which had exhibited signs of stem galling and packing leakage on May 19, 1991. We had previously (December 14, 1990) requested a change in Technical Specifications deleting the requirements of TS 4.7.D.1.c. The TWOC is to remain in effect until this proposed TS change can be acted on by the NRC.

Your staff has asked us to confirm that we will take measures to detect any further degradation of the valve prior to its becoming inoperable and will take actions at the next refueling outage to correct the problem prior to restart. The following actions will be taken in order to maintain a high degree of reliability for MSIVs at the DAEC.

We will use the results of the quarterly fast closure and reopening test required by TS 4.7.D.1.b(2) to trend the opening and closing stroke time of MSIV CV-4419 to detect any further degradation. We will evaluate steam tunnel temperatures for significant change on a daily basis and trend these temperatures on a weekly basis until the next refueling outage (Cycle 11/12) currently scheduled to begin March 2, 1992. Steam tunnel temperatures are routinely read once per shift. The daily evaluation and weekly trending of these readings will enable us to monitor any changes in steam tunnel temperature. Changes in steam tunnel temperature may indirectly indicate

2107030039 210624  
PDR ADDCK 05000331  
PDR

020011

ADD 11

Mr. Thomas E. Murley  
June 24, 1991  
NG-91-1594  
Page 2

further degradation of MSIV CV-4419. Also, routine inspections of the steam tunnel area will provide us an alternate opportunity to detect any noticeable increases in steam leakage from this valve. However, due to ALARA and personnel safety concerns detailed visual inspections will not be performed unless there are other indications of further degradation due to stem galling before the next refueling outage. We will inspect and repair the MSIV in question during the next refueling outage. A root cause analysis of this problem will be performed prior to the Cycle 12 startup in order to determine whether any additional corrective actions need to be taken to minimize the potential for recurrence of this problem.

If you have any questions regarding this matter, please contact this office.

Very truly yours,



Daniel L. Mineck  
Manager, Nuclear Division

DLM/DJM/pjv+

cc: D. Mienke  
L. Liu  
L. Root  
R. McGaughy  
C. Shiraki (NRC-NRR)  
A. Bert Davis (Region III)  
NRC Resident Office