

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9109030210 DOC.DATE: 91/08/23 NOTARIZED: NO DOCKET #  
FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331  
AUTH.NAME AUTHOR AFFILIATION  
MINECK,D.L. Iowa Electric Light & Power Co.  
RECIP.NAME RECIPIENT AFFILIATION  
MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411

SUBJECT: Advises that util will no longer perform disassembly/insp of feedwater check valves V-14-1 & V-14-3,per 1990 submittal unless local leak rate test results indicate insps appropriate.

DISTRIBUTION CODE: A017D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1  
TITLE: OR Submittal: Append J Containment Leak Rate Testing

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD3-3 LA	1	0	PD3-3 PD	1	1
	HALL,J.R.	2	2			
INTERNAL:	ACRS	6	6	NRR/DST/SPLB 8D	1	1
	OC/LFMB	1	0	OGC/HDS2	1	1
	REG. FILE 01	1	1	RES/DE/SEB	1	1
	RES/DRA/RDB/RS	1	1	RES/DSIR/SAIB	1	1
	RES/DSR/RPSB	1	1			
EXTERNAL:	NRC PDR	1	1	NSIC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL ~~18~~ 0

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S

Iowa Electric Light and Power Company

August 23, 1991  
NG-91-2237


Dr. Thomas E. Murley, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

Subject: Duane Arnold Energy Center  
Docket No: 50-331  
Op. License No: DPR-49  
Feedwater Check Valve Disassembly and  
Inspection Commitment  
Reference: Letter from D. Mineck (Iowa Electric) to  
T. Murley (NRC) dated April 2, 1990  
(NG-90-0833)  
File: A-105, T-23i

Dear Dr. Murley:

The referenced 1990 letter stated that we would disassemble and inspect Feedwater Check Valves (V-14-1 and V-14-3) each refueling outage. This preventive maintenance was undertaken because the material of the soft seats was subject to degradation over time. Since that letter was submitted to the NRC, the soft seats have been removed from these valves. Therefore, disassembly is no longer warranted unless it is indicated by the results of local leak rate tests (LLRTs). Consequently, we no longer intend to perform the inspections referred to in the 1990 submittal unless LLRT results indicate that they are appropriate.

Should you have any questions regarding this matter, please contact this office.

Very truly yours,  


Daniel L. Mineck  
Manager, Nuclear Division

DLM/CJR/pjv\*

cc: C. Rushworth  
L. Liu  
L. Root  
R. McGaughy  
C. Shiraki (NRC-NRR)  
A. Bert Davis (Region III)  
NRC Resident Office

300008

AD17 / 10

9109030210 910823  
PDR ADDCK 050000331  
PDR