

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 7028

FILE: Occu

FROM: Northern States Power Company Minneapolis, Minn. 55401 Mr. C.E. Larson		DATE OF DOC 9-18-73	DATE REC'D 9-18-73	LTR	MEMO	RPT	OTHER Telecopy
TO: Mr. Keppler		ORIG 1	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-263		

DESCRIPTION:
Ltr advising AEC of an abnormal occurrence which occurred on 9-17-73 concerning the lubricating oil in the No. 12 Standby liquid Control pump crankcase which was found to be contaminated with sodium pentaborate solution.

PLANT NAME: Monticello Unit #1

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

FOR ACTION/INFORMATION 9-19-73 JB



- | | | | |
|------------------------|---------------------------|---|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | <input checked="" type="checkbox"/> ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

- | | | | |
|--|---|-------------|---|
| <input checked="" type="checkbox"/> REG FILE | <input checked="" type="checkbox"/> TECH REVIEW | DENTON | A/T IND |
| <input checked="" type="checkbox"/> AEC PDR | <input checked="" type="checkbox"/> HENDRIE | GRIMES | BRAITMAN |
| <input checked="" type="checkbox"/> OGC, ROOM P-506A | <input checked="" type="checkbox"/> SCHROEDER | GAMMILL | <input checked="" type="checkbox"/> DIGGS (L) |
| <input checked="" type="checkbox"/> MUNTZING/STAFF | <input checked="" type="checkbox"/> MACCARY | KASTNER | GEARIN (L) |
| <input checked="" type="checkbox"/> CASE | <input checked="" type="checkbox"/> KNIGHT | BALLARD | GOULBOURNE (L) |
| GIAMBUSSO | <input checked="" type="checkbox"/> PAWLICKI | SPANGLER | LEE (L) |
| BOYD | <input checked="" type="checkbox"/> SHAO | | MAIGRET (L) |
| MOORE (L)(BWR) | <input checked="" type="checkbox"/> STELLO | ENVIRO | SERVICE (L) |
| DEYOUNG(L)(PWR) | <input checked="" type="checkbox"/> HOUSTON | MULLER | SHEPPARD (E) |
| <input checked="" type="checkbox"/> SKOVHOLT (L) | <input checked="" type="checkbox"/> NOVAK | DICKER | SMITH (L) |
| P. COLLINS | <input checked="" type="checkbox"/> ROSS | KNIGHTON | TEETS (L) |
| | <input checked="" type="checkbox"/> IPPOLITO | YOUNGBLOOD | WADE (E) |
| <input checked="" type="checkbox"/> REG OPR | <input checked="" type="checkbox"/> TEDESCO | REGAN | WILLIAMS (E) |
| FILE & REGION(3) | <input checked="" type="checkbox"/> LONG | PROJECT LDR | WILSON (L) |
| <input checked="" type="checkbox"/> MORRIS | <input checked="" type="checkbox"/> LAINAS | | |
| <input checked="" type="checkbox"/> STEELE | <input checked="" type="checkbox"/> BENAROYA | HARLESS | |
| | <input checked="" type="checkbox"/> VOLLMER | | |

EXTERNAL DISTRIBUTION

- | | | |
|--|-----------------------------------|---------------------------|
| <input checked="" type="checkbox"/> 1 - LOCAL PDR Minneapolis, Minn. | (1) (2) (10) - NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| <input checked="" type="checkbox"/> 1 - DTIE (ABERNATHY) | 1 - R. Schoonmaker, OC, GT, D-323 | 1 - GERALD LELLOUCHE |
| <input checked="" type="checkbox"/> 1 - NSIC (BUCHANAN) | 1 - W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB (YORE/SAYRE/
WOODARD/"H" ST. | 1 - CONSULTANT'S | 1 - AGMED (WALTER KOESTER |
| <input checked="" type="checkbox"/> 16 - CYS ACRS XXXXXXXX Sent to Diggs
9-19-73 | NEWMARK/BLUME/AGBABIAN | RM-C-427-GT |
| | 1 - GERALD ULRIKSON... ORNL | 1 - RD..MULLER..F-309-GT |



v

cc'd 9-18-73
4:00 p.m.

NRIP

Regulatory File Cy.

NORTHERN STATES POWER COMPANY

Dear Mr. Koppier:

**MORTICELLO NUCLEAR GENERATING PLANT
Docket No. 80-265 License No. DWR-22**

On September 17, 1973, the lubricating oil in the No. 12 Standby Liquid Control pump crankcase was found to be contaminated with sodium pentaborate solution. It was determined that the stuffing box drain valve had been closed on or about September 12th for painting of the pump mounting base. The normal pump packing leakage then backed up in the stuffing box until it overflowed into the crankcase through the plunger stub ports.

The crankcase was drained, flushed, and refilled with fresh oil.

Yours very truly,

C. E. Larson

C. E. Larson
Plant Manager

CEM/rik

cc: J. P. O'Leary, Directorate of Monitoring
G. Charnoff
Minnesota Pollution Control Agency
Attn: Ken Dugan
File

Copies sent by telecopier to Koppier and O'Leary



Regulatory
File Cy.