

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  
Greater Flint Imaging  
G-1071 North Bellenger Highway, Suite 312  
Flint, Michigan 48504  
REPORT NUMBER(S): 11-01

2. NRC/REGIONAL OFFICE  
U.S. Nuclear Regulatory Commission, Region III  
2443 Warrenville Road, Suite 210  
Lisle, Illinois 60532

3. DOCKET NUMBER(S)  
030-18247

4. LICENSEE NUMBER(S)  
21-20320-01

5. DATE(S) OF INSPECTION  
October 4, 2011

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Andrew M. Bramnik	<i>Andrew M. Bramnik</i>	10/4/2011
Branch Chief	Tamara E. Bloomer	<i>T. Bloomer</i>	10/13/11

*Docket File Information*  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE Greater Flint Imaging  REPORT NUMBER(S) 11-01	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532
--	---

3. DOCKET NUMBER(S) 030-18247	4. LICENSEE NUMBER(S) 21-20320-01	5. DATE(S) OF INSPECTION October 4, 2011
----------------------------------	--------------------------------------	---

6. INSPECTION PROCEDURES 87131	7. INSPECTION FOCUS AREAS 03.01 – 03.07
-----------------------------------	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM 2200	2. PRIORITY 3	3. LICENSEE CONTACT AppaRao Mukkamala, M.D. – RSO	4. TELEPHONE NUMBER 810-235-0668
--------------------	------------------	--	-------------------------------------

Main Office Inspection  
 Field Office Inspection  
 Temporary Job Site Inspection

Next Inspection Date: October 2014

**PROGRAM SCOPE**

This was a routine inspection of a private clinic that performed approximately 14 diagnostic nuclear medicine procedures per week. Two full time nuclear medicine technologists performed all patient procedures Monday through Thursday. The licensee obtained licensed material as unit doses from an area nuclear pharmacy, and did not use xenon-133, bulk doses, or molybdenum/technetium generators. The licensee performed primarily bone, whole body, HIDA, and thyroid uptake scans. Although the licensee was authorized to administer therapeutic doses of licensed material under Title 10 of the Code of Federal Regulations (10 CFR) Section 35.300, the licensee had not used iodine-131 since before the previous inspection in November 2008. The licensee informed the inspector that they intended to remove this authorization from their NRC license.

**PERFORMANCE OBSERVATIONS**

Interviews of available staff revealed an adequate level of understanding of emergency and material handling procedures and techniques. Dose calibrator constancy checks, package receipt, daily area surveys, and waste handling and disposal procedures were successfully demonstrated. An outside consultant performed quarterly program audits that were adequate to oversee the program. The radiation safety officer (RSO) worked at an area hospital and visited the clinic approximately monthly.

Licensed material was adequately secured and not readily accessible to members of the general public. The licensee possessed a radiation survey meter that was calibrated and operational. Independent measurements did not indicate readings in excess of 10 CFR Part 20 limits in restricted or unrestricted areas. Personal whole body and extremity dosimetry were observed worn by the staff during the inspection, and records did not indicate doses in excess of 10 CFR Part 20 limits. Dosimetry records indicated that the highest annual whole body and extremity readings since the previous inspection were 51 millirem (mrem) and 264 mrem, respectively.

No violations were identified during this inspection.