Docket No. 50-263

AUG 2 3 1977

DISTRIBUTION:
Docket
NRC PDR
Local PDR
ORB-2 Reading
RPSnaider
RMDiggs
DEisenhut
Attorney, OELD
I&E (3)
JRBuchanan
TBAbernathy
TJCarter
ACRS (16)

Northern States Power Company ATTN: Mr. L. O. Mayer, Manager Nuclear Support Services 414 Nicollet Mall - 8th Floor Minneapolis, Minnesota 55401

Gentlemen:

RE: MONTICELLO NUCLEAR GENERATING PLANT

The NRC has completed its initial evaluation of the BWR feedwater nozzle and control rod drive (CRD) line return nozzle cracking phenomena and experience to date. This evaluation has considered examination results reported by BWR owners, theoretical analyses of the causes of the cracking and propagation, and studies of potential remedial measures to minimize crack initiation and growth for the short term and also to eliminate the causes of cracking for the longer term. The enclosed staff report presents our position regarding feedwater nozzle and CRD nozzle cracking and includes inspection criteria to be used by licensees to monitor crack growth until such time as the causes of cracking have been eliminated.

Although you have already made us aware of your tentative plans for nozzle inspection and repair during the forthcoming Monticello 1977 refueling outage, and we expect to continue discussion of this subject in the near future, you should especially note the requested information submittals of Part I, Section 7 and Part II Section 5. These submittals should be provided prior to each outage subsequent to the Fall, 1977 outage.

Original signed by

Don K. Davis, Acting Chief

Operating Reactors Branch #2 Division of Operating Reactors

Enclosure: Staff Report

cc w/enclosure:



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

August 23, 1977

Docket No. 50-263

Northern States Power Company ATTN: Mr. L. O. Mayer, Manager Nuclear Support Services 414 Nicollet Mall - 8th Floor Minneapolis, Minnesota 55401

Gentlemen:

RE: MONTICELLO NUCLEAR GENERATING PLANT

The NRC has completed its initial evaluation of the BWR feedwater nozzle and control rod drive (CRD) line return nozzle cracking phenomena and experience to date. This evaluation has considered examination results reported by BWR owners, theoretical analyses of the causes of the cracking and propagation, and studies of potential remedial measures to minimize crack initiation and growth for the short term and also to eliminate the causes of cracking for the longer term. The enclosed staff report presents our position regarding feedwater nozzle and CRD nozzle cracking and includes inspection criteria to be used by licensees to monitor crack growth until such time as the causes of cracking have been eliminated.

Although you have already made us aware of your tentative plans for nozzle inspection and repair during the forthcoming Monticello 1977 refueling outage, and we expect to continue discussion of this subject in the near future, you should especially note the requested information submittals of Part I, Section 7 and Part II Section 5. These submittals should be provided prior to each outage subsequent to the Fall, 1977 outage.

Sincerely,

Don K. Davis, Acting Chief Operating Reactors Branch #2 Division of Operating Reactors

Enclosure: Staff Report

cc w/enclosure:
See next page

cc Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 1800 M Street, N. W. Washington, D. C. 20036

Arthur Renquist, Esquire Vice President - Law Northern States Power Company 414 Nicollet Mall Minneapolis, Minnesota 55401

Howard J. Vogel, Esquire Legal Counsel 2750 Dean Parkway Minneapolis, Minnesota 55416

Mr. Kenneth Dzugan Environmental Planning Consultant Office of City Planner Grace Building 421 Wabasha Street St. Paul, Minnesota 55102

Sandra S. Gardebring
Executive Director
Minnesota Pollution Control Agency
1935 W. County Road B2
Roseville, Minnesota 55113

Anthony Z. Roisman, Esquire Roisman, Kessler and Cashdan 1025 15th Street, N. W., 5th Floor Washington, D. C. 20005

The Environmental Conservation Library Minneapolis Public Library 300 Nicollet Mall Minneapolis, Minnesota 55401