

Recent Licensee Event Report (LER) Search Results - for "Seismic" related LERs
(Jan-26-2009 and Jan-26-2011) – 18 LERs

NOTE: This document is referenced from and supports Information Notice 2012-01 "SEISMIC CONSIDERATIONS—PRINCIPALLY ISSUES INVOLVING TANKS" issued under Agencywide Documents and Management System (ADAMS) Accession Number: [ML1129A175](#)

LER Active Hyper-link	Event Date	Plant /Unit #	Title/ Brief Description
2372009008	11/03/2009	Dresden 2	Unit 2 Core Spray Break Detection Instrument Line Not Seismically Supported
2702010001	07/02/2010	Oconee 2	Operation Prohibited by TS due to Removal of West Penetration Room Brick Wall Support Girts
2772010002	09/18/2010	Peach Bottom 2, Peach Bottom 3	Improperly Fastened Rod Hanger Results in Inoperable Subsystem of Emergency Service Water
2932010001	01/10/2010	Pilgrim	Single Train of Reactor Building Closed Cooling Water System Inoperable for Time Period Exceeding Technical Specification Limits
3312010006	11/10/2010	Duane Arnold	Standby Liquid Control Test Tank Seismic Analysis
3382010005	12/12/2010	North Anna 1	Unanalyzed Scaffolding Renders Charging Pump Inoperable due to Human Error
3612009002	03/28/2009	San Onofre 2, San Onofre 3	Inoperable 1E Breaker Causes Containment Chiller to be Inoperable
3612009003	09/29/2009	San Onofre 2	Pressurizer Auxiliary Spray Failed Inservice Test
3612010001	01/26/2010	San Onofre 2	Broken Manual Valve Prevents Timely Condensate Storage Tank Isolation
3612010002	05/12/2010	San Onofre 2	Non-qualified Part in Turbine Driven Auxiliary Feedwater Pump
3612010005	10/13/2010	San Onofre 2, San Onofre 3	Refueling Water Storage Tank Alignment to Non-Seismic Piping Results in Potential Loss of Safety Function
3612010006	10/13/2010	San Onofre 2, San Onofre 3	Breakers Left in Non-Seismically Qualified Condition Result in Condition Prohibited by Technical Specifications
3642009001	10/06/2009	Farley 2	Service Water Pump Seismic Supports Degraded
3732010003	10/28/2010	LaSalle 1, LaSalle 2	Standby Liquid Control Test Tank Seismic Analysis
4002010003	09/16/2010	Harris	Condition Prohibited by Technical Specifications When Non-seismic System Was Aligned to Refueling Water Storage Tank
4552010002	06/04/2010	Byron 2	Essential Service Water System Inoperable Due to Inadequate Seismic Restraint from Original Construction Error
4822010010	09/22/2010	Wolf Creek	Inadequate Analysis Results in a Component Cooling Water Train to be Declared Inoperable
4832010008	09/23/2010	Callaway	Inadequate Analysis Results in a Component Cooling Water Train Declared Inoperable

LER Search Restrictions:

Status: Active
Event Dates: between Jan-26-2009 and Jan-26-2011
Keyword(s): seismic
Keyword Scope: Title and Abstract