

NSP

N O R T H E R N S T A T E S P O W E R C O M P A N Y

Minneapolis, Minnesota 55401

December 12, 1979

Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Drywell Safe Shutdown Analysis Required
by Fire Protection Safety Evaluation

Sections 3.2.8 and 5.12.6 of the Monticello Fire Protection Safety Evaluation Report issued by the NRC Staff on August 29, 1979 contain our commitment to reevaluate the drywell area relative to safe shutdown requirements of equipment and cables in this area. In order to complete this evaluation it will be necessary to perform an inspection of the drywell. This inspection will be performed during the February 1980 refueling outage. Results of this reevaluation will be provided to the Staff by March 31, 1980. Please contact us if you require additional information.



L. O. Mayer, PE
Manager of Nuclear Support Services

cc: J. G. Keppler
G. Charnoff

*Ac006
12/10*

F 7912190 167