

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8110060203 DOC. DATE: 81/09/28 NOTARIZED: NO DOCKET #  
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263  
 AUTH. NAME: AUTH. AFFILIATION  
 MAYER, L. O. Northern States Power Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 Office of Nuclear Reactor Regulation, Director

SUBJECT: Forwards rept addressing equipment qualification  
 deficiencies noted in NRC 810603 safety evaluation.  
 Evaluation of incomplete items will be submitted by 811101. *See Rpt*

DISTRIBUTION CODE: A048S COPIES RECEIVED: LTR 1 ENCL 40 SIZE: 1+76  
 TITLE: Equipment Qualification (OR & PRE-OL)

## NOTES:

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME	LTR
ACTION:	ORBI #2 BC	12	6	6	ECCLESTAN, K.	01	1
INTERNAL:	DIR/DOL	12	1	1	EQUIP. QUAL BR07		5
	I&E	18	3	3	DELD	20	1
	UGC	21	1	1	REG FILE	04	1
	WILLIAMS, M. H.	06	1	1			
EXTERNAL:	ACRS	23	16	16	LPDR	03	1
	NRC PDR	02	1	1	NSIC	05	1
	NTIS		1	1			

OCT 09 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 40 ENCL 40



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

September 28, 1981

Director of Nuclear Reactor Regulation  
US Nuclear Regulatory Commission  
Washington, DC 20555

Monticello Nuclear Generating Plant  
Docket No. 50-263 License No. DPR-22



Response to IE Bulletin 79-01B Safety Evaluation Report

Attached is a report prepared by EDS Nuclear Corporation which addresses the deficiencies in equipment qualification identified in the Safety Evaluation Report (SER) prepared by the Office of Nuclear Reactor Regulation, Equipment Qualification Branch, USNRC, for the Monticello Nuclear Generating Plant. This SER was provided to us in a letter dated June 3, 1981 from Mr Thomas A Ippolito, Chief, Operating Reactors Branch #2.

The attached report is a complete response except for the following items:

- a. Radiation conditions inside containment are still being evaluated (see p. 3-9).
- b. Flooding outside containment from a high energy line break is still being evaluated (see p. 3-11).
- c. The component evaluation worksheets are not completed.

Incomplete items will be submitted by November 1, 1981 in a revision to the attached report. Please contact us if you have any questions related to our report or plans and schedule for resolving this issue.

L O Mayer, PE  
Manager of Nuclear Support Services

cc: J G Keppler  
NRC Resident Inspector  
G Charnoff

attachment

*Handwritten:* 1048  
5-1/40

8110060203 810928  
PDR ADCK 05000263  
Q PDR