

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Eye Lighting Int'L of North America 9150 Hendricks Road Mentor, Ohio 44060 REPORT NUMBER(S) 11-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------

3. DOCKET NUMBER(S) 030-35694	4. LICENSE NUMBER(S) 34-23877-01E	5. DATE(S) OF INSPECTION 11/28/2011
-----------------------------------------	---------------------------------------------	-----------------------------------------------

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Bill Lin/Ken Lambert	<i>Bill Lin/Ken Lambert</i>	12/7/11
BRANCH CHIEF	Tamara Bloomer	<i>Tamara Bloomer</i>	12/8/11

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Eye Lighting Int'L of North America
9150 Hendricks Road
Mentor, Ohio 44060

REPORT NUMBER(S) 11-01

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-35694

4. LICENSE NUMBER(S)

34-23877-01E

5. DATE(S) OF INSPECTION

11/28/2011

6. INSPECTION PROCEDURES USED

87125

7. INSPECTION FOCUS AREAS

3.01-3.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

03251

2. PRIORITY

5

3. LICENSEE CONTACT

John Hecht

4. TELEPHONE NUMBER

(440) 350-7000

Main Office Inspection

Next Inspection Date: 10/2016

Field Office Inspection

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee is a distributor of light bulbs containing Krypton (Kr) 85. The Licensee receives the light bulbs from its parent firm in Japan for distribution within the United States. These light bulbs contain krypton as an enhancement to light output. Material is possessed under a state of Ohio license. The license granted by the NRC is for distribution only and does not authorize possession of material.

Performance Observations

Licensee demonstrated and discussed how the light bulbs are stored and accounted for in its inventory system. The licensee was able produce its record of the number of units shipped in the past twelve months for the inspectors. Interviews of the licensee's personnel indicated an adequate level of knowledge of radiation safety.

The inspectors was able to verify that each unit containing Kr-85 was labeled in according with the licensee's license condition. The inspector took confirmatory survey and no radiation readings were above regulatory compliance limits. Licensee personnel are not required to wear dosimetry. No violations of requirements were noted.