2.201	SAFETY	INSPECTION			
Halliburton Industrial Services, Inc. 1015 Bois D'Arc Duncan, Oklahoma 73536		2. REGIONAL C	2. REGIONAL OFFICE		
		U.S. Nuclear Regulatory Commission 611 Ryan Plaza Dr. Suite 1000 Arlington, Texas 76011			
DOCKET NUMBER(S)	4. LICENSE NUMBER	(5)	5. DATE OF INSPECTION		
030-20094			02-05 October 19, 1983		
censee:					
mulatory Commissions (NRC) rules and res	pulations and the conditions of ersonnel, and observations by t	your license. The in-	to radiation safety and to compliance with t spection consisted of selective examinations indings as a result of this inspection are as fo	of procedures	
The inspector also verified the steps ye those actions at this time.	ou have taken to correct the vid	plations identified du	ring the last inspection. We have no further	questions on	
		- · · · · · · · · · · · · · · · · · · ·	20		
3. During this inspection certain of your THIS IS A NOTICE OF VIOLATION					
^			was not properly posted to indic	ate the presence	
			. 10 CFR 20.203(b), (c), (
				t-	
B. Containers located in	-	20 202/5//11 or /5//2		ere not properly	
labeled to indicate the presence of		20.203(17(7), 6) (17(2			
			of sealed sources were not perform	ed at the proper	
frequencies. 10 CFR		Lic	cense Condition Number		
y D. Records of personne	l exposures		were not prop	- erly maintained.	
10 CFR		_ or License Condit			
E. Documents were not properly post					
F. Reports or notifications of			were not made	de in accordance	
with 10 CFR		or License Condit	ion Number		
			for inspection at the lie		
1					
J					
ereby state that within 30 days the actions	described by me to the inspect	or Will be taken to c	orrect the violations identified in the items	checked above	
			O1. No further response will be submitted u		
The Chris	1	V.	Blu Suthery	11/1/83	
SIGNATURE - LICENSEE	DATE	sigi	NATURE - NAC INSPECTOR	DATE	