



PSEG Power, LLC  
PSEG Site ESPA  
Part 2, Site Safety Analysis Report  
Water Surface Elevations at the New  
Plant Location Following Failure of the  
Cannonsville and Pepacton Dams  
**FIGURE 2.4.4-3** Rev. 0