Davis-BesseHearingFile Resource

From:

CuadradoDeJesus, Samuel

Sent:

Tuesday, October 11, 2011 5:32 PM

To:

Sheikh, Abdul; Lehman, Bryce

Cc: Subject: Davis-BesseHearingFile Resource FW: Davis-Besse Shield Building Crack

Attachments:

CR 2011-03346.pdf

FYI

From: Jose, Benny

Sent: Tuesday, October 11, 2011 4:50 PM

To: CuadradoDeJesus, Samuel

Subject: FW: Davis-Besse Shield Building Crack

FYI

From: Stone, AnnMarie

Sent: Tuesday, October 11, 2011 3:38 PM

To: Jose, Benny

Subject: FW: Davis-Besse Shield Building Crack

From: Wilson, Adam

Sent: Tuesday, October 11, 2011 10:37 AM

To: Smagacz, Phillip; Kimble, Daniel

Cc: Steffes, Jakob; Rutkowski, John; Cameron, Jamnes; Briley, Thomas; Stone, AnnMarie; Holmberg, Mel; Neurauter,

James; Mitlyng, Viktoria; Chandrathil, Prema Subject: RE: Davis-Besse Shield Building Crack

Here is the CR the licensee wrote, which gives some of the detail of the size of the crack.

From: Smagacz, Phillip

Sent: Tuesday, October 11, 2011 10:03 AM

To: Wilson, Adam; Kimble, Daniel

Cc: Steffes, Jakob; Rutkowski, John; Cameron, Jamnes; Briley, Thomas

Subject: Davis-Besse Shield Building Crack

Gentlemen.

I had a request from Ann-Marie Stone to include her in any email traffic/discussion regarding the shield building crack since it may have implications for license renewal.

Thanks, Phillip Smagacz Reactor Engineer RIII/DRP-PB6 (630) 829-9832 phillip.smagacz@nrc.gov

s स्थापित ।				Part of the second	
eracianina San Ma	APPORTUNE SEL		owning on this hope	TOTAL THE PER	And the second second
CR-2011-03346	10/10/2011	Maria Maria Maria	DB-EN	FL-PR-DB	
	category - 12	-	A TOTAL	W. Wolf Bridge	
G201 1	AA	CONTRACTOR OF THE PARTY OF THE	CONTRACTOR OF THE PROPERTY OF	STATE OF THE PROPERTY.	2 Control of the Cont
THE CAUCY	1	-10944 - CS-178		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	W-1
Fractured Concrete Found at 17M	Shield Building Con			49: A) V. (1.2. N. (1	Contract Con
Discover Date Value	Discover Time			Event T	me de la companya de
10/10/2011	20:21		10/10/2011	20:21	
Functional Location - System	W		Functional Location	V III III II II II II	
		10.00	Patientalion contraction	33.04	127-304-30-30-30-30-30-30-30-30-30-30-30-30-30-
Equipment Description	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- T	AP-913	EP FOUI	pment .
	35312 38 5 5 5 15 8	F	AL BEC 2 . AMBERTULA SERVICES		PHILODE N. PRICE.
Identified By	医腹部 海上水源 1	Late Control of	QA Finding?	SRO Re	view.Required.but.
Individual			No	The Later of the L	Skipped as a State of the Skipped as a state
				No	
gentelliten kiennen	A SECTION OF THE PERSON	er salaksan an			3.2
Description of condition and	Probable Cause		Market Market		AND THE PARTY OF T
During Hydro-demolition operation					
were identified at the bottom of th	e opening near the	left corner (facil	ng inward), at the top of th	e opening at the u	pper left corner (facing
inward), and at the left side of the	opening (facing inw	vard) a vertical cr	ack along the inner layer o	f rebar was found	H.Sawa VIII . Bacana da Bara . A
Immediate Actions Taken	TANK TELL		Partie William William	y to the	· (1)
A Bechtel Condition Report (25539	-000-GCA-GAMG-0	0182) was writte	n to identify this condition	. FENOC SGR Proj	ect Manager and Design
Engineering Manager were notified Recommended Actions	i. PENOC Design En	igineering and pr	oject personnei with Bech	tei inspected the c	Ondition.
Recommended Actions	The state of the s	A TOTAL AND	Alternative Control		**************************************
State of the		Taga era era		0.000	
Contact - Sales - Contact			A PART OF THE PROPERTY OF THE PART OF THE	C. With the San	
	April 1	4.399	A STATE OF THE PARTY OF THE PAR	A	
h = = .					
hook	a conject	Page 1 Sample	water the same of the same of the same		· 多多数, 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Supervisor Comments	- Y L			. 13 (.	20 % 10 4 10 10 10 10 10 10 10 10 10 10 10 10 10
Supervisor Comments Inspected the construction opening	. A small crack (in	width) is located	along the left side of the o		present for
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 I	g. A small crack (in of the opening unt detail 1). The hydro	width) is located il it diminishes. I demolition has	along the left side of the of The crack is located adjaces removed the concrete past	nt to the "architec t the location of th	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspection opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will not continuing the continuing hydro demolition will not continue the continue	G. A small crack (in of the opening unt betail 1). The hydro of impact the crack.	width) is located il it diminishes. I demolition has The crack will s	along the left side of the of The crack is located adjaces removed the concrete past	nt to the "architec t the location of th	present for tural flute" area on the e crack. Therefore,
Inspervisor Comments Inspervisor the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities	y. A small crack (in of the opening unt betail 1). The hydro ot impact the crack. on activity can proc	width) is located il it diminishes. I demolition has The crack will s eed.	along the left side of the of The crack is located adjacer removed the concrete past till be available for inspecti	nt to the "architec the location of th on / investigation	present for tural flute" area on the e crack. Therefore,
Inspervisor Comments Inspervisor the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities this a consequential Human	A small crack (in of the opening unt betail 1). The hydro of impact the crack on activity can proc	width) is located il it diminishes. demolition has The crack will s eed. Tror/Event	along the left side of the of The crack is located adjacet removed the concrete past till be available for inspecti SRO Review Required	nt to the "architec the location of th on / investigation	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will not recommended that hydro demoliticity this a consequential Human which requires a Quick Human	A small crack (in of the opening unt betail 1). The hydro of impact the crack on activity can proc	width) is located il it diminishes. demolition has The crack will s eed. Tror/Event	along the left side of the of The crack is located adjacer removed the concrete past till be available for inspecti	nt to the "architec the location of th on / investigation	present for tural flute" area on the e crack. Therefore,
Inspervisor Comments Inspervisor the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities this a consequential Human	A small crack (in of the opening unt betail 1). The hydro of impact the crack on activity can proc	width) is located il it diminishes. I demolition has The crack will seed. Tror/Event Checklist?	along the left side of the of the crack is located adjacet removed the concrete past till be available for inspecti SRO Review Required Yes	nt to the "architec the location of th on / investigation	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No	g. A small crack (in of the opening unt betail 1). The hydro ot impact the crack. on activity can proc i Performance E in Rerformance (width) is located if it diminishes. It demolition has the crack will seed. TOTE EVENT. Lecklist?	along the left side of the of the crack is located adjacet removed the concrete past till be available for inspecti SRO Review Required Yes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No	A small crack (in of the opening unt betail 1). The hydro of impact the crack on activity can proc	width) is located il it diminishes. I demolition has The crack will seed. Tror/Event Checklist?	along the left side of the of the crack is located adjacet removed the concrete past till be available for inspecti SRO Review Required Yes	nt to the "architec the location of th on / investigation	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities this a consequential Human which requires a Quick Human No	A small crack (in of the opening unt betail 1). The hydro to impact the crack on activity can proc n Performance E n Performance	width) is located il it diminishes. It demolition has The crack will s eed. TOF/Event Checklist? Event	along the left side of the c The crack is located adjace removed the concrete past till be available for inspecti SRO Review Required Yes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore,
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities this a consequential Human which requires a Quick Human No	A small crack (in of the opening unt betail 1). The hydrot impact the crack on activity can process Performance For Performance Activity	width) is located if it diminishes. It demolition has The crack will seed. TOF/Event Checklist? Event tivity / Proces	along the left side of the c The crack is located adjace removed the concrete past till be available for inspecti SRO Review Required Yes Codes Codes Codes Codes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 continuing hydro demolition will no recommended that hydro demolities this a consequential Human which requires a Quick Human No	A small crack (in of the opening unt betail 1). The hydrot impact the crack on activity can process a Performance For Performa	width) is located if it diminishes. It demolition has The crack will seed. TOF/Event Checklist? Event tivity / Proces	along the left side of the c The crack is located adjace removed the concrete past till be available for inspecti SRO Review Required Yes Codes Codes Codes Codes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Huma No EQ03; Structural	A small crack (in of the opening unt betail 1). The hydrot impact the crack on activity can process a Performance For Performa	width) is located if it diminishes. It demolition has The crack will seed. TOF/Event Checklist? Event tivity / Proces	along the left side of the c The crack is located adjace removed the concrete past till be available for inspecti SRO Review Required Yes Codes Codes Codes Codes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No EQ03; Structural Activity Code Related Pro Qualification and	A small crack (in of the opening unt betail 1). The hydrot impact the crack on activity can process a Performance For Performa	width) is located if it diminishes. It demolition has The crack will seed. TOF/Event Checklist? Event tivity / Proces	along the left side of the c The crack is located adjace removed the concrete past till be available for inspecti SRO Review Required Yes Codes Codes Codes Codes	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Supervisor Comments Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Huma No EQ03; Structural ACLIVITY CODE Related Pro 1500; Equipment CC0	A small crack (in of the opening unt betail 1). The hydrot impact the crack on activity can process a Performance For Performa	width) is located if it diminishes. It demolition has the crack will seed. ITOT/Event Event Event tivity / Proces	along the left side of the crack is located adjaceremoved the concrete past till be available for inspection of the concrete past till be available for insp	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 Continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No EQ03; Structural Activity Code Related Pro Qualification and Asset Maintenance	A small crack (in of the opening unt petail 1). The hydrost impact the crack on activity can proce in Performance in Performan	width) is located if it diminishes. It demolition has the crack will seed. ITOY/Event Event Event Event (Event Code Data)	along the left side of the crack is located adjaceremoved the concrete past till be available for inspection of the concrete past till be available for insp	nt to the "architect the location of the locat	present for tural flute" area on the e crack. Therefore, Therefore, it is
Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 L continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No EQ03; Structural Activity Code Related Pro 1500; Equipment Qualification and Asset Maintenance Event Status	A small crack (in of the opening unt petall 1). The hydrost impact the crack on activity can proce in Performance in Performance in Regional Cause Code Cause	width) is located if it diminishes. It diminishes. It demolition has the crack will seed. ITOT/Event. Checklist? Event (Event. Livity / Procese Code Data Workbook Created by	along the left side of the crack is located adjaceremoved the concrete past till be available for inspection of the concrete past till be available for insp	nt to the "architect the location of the locat	resent for tural flute" area on the e crack. Therefore, it is Related one life Actions
Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 L continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No EQ03; Structural Activity Cod Activity Cod Activity Cod Status Initiate Completed	Asmall crack (in of the opening unt of the opening unt opening in the hydrotrimpact the crack on activity can proceed to the crack of t	width) is located if it diminishes. It diminishes. It demolition has the crack will seed. ITOT/EVENT. EVENT. Livity / Procese Code Data Workbood Created by Wallis, James	along the left side of the crack is located adjaceremoved the concrete past till be available for inspection of the concrete past till be available for insp	to the "architect the location of the location	resent for tural flute" area on the e crack. Therefore, it is Related corrective Actions 10/10/2011 20:52 EDT
Inspected the construction opening approximately 8 feet along the top outside (reference drawing C-110 L continuing hydro demolition will no recommended that hydro demolitic is this a consequential Human which requires a Quick Human No EQ03; Structural Activity Code Related Pro 1500; Equipment Qualification and Asset Maintenance Event Status	A small crack (in of the opening unt petall 1). The hydrost impact the crack on activity can proce in Performance in Performance in Regional Cause Code Cause	width) is located if it diminishes. It diminishes. It demolition has the crack will seed. ITOT/Event. Checklist? Event (Event. Livity / Procese Code Data Workbook Created by	along the left side of the crack is located adjaceremoved the concrete past till be available for inspection of the concrete past till be available for insp	nt to the "architect the location of the locat	resent for tural flute" area on the e crack. Therefore, it is Related one life Actions