

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: V. Goburdhun, M.D. P.C. 14555 Levan Road Suite 403 Livonia, MI 48154 REPORT NUMBER(S) 12-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-36054	4. LICENSE NUMBER(S) 21-32408-01	5. DATE(S) OF INSPECTION 07/27/2012
----------------------------------	-------------------------------------	--

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 3.01-3.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Ashok B. Jain, M.D., RSO	4. TELEPHONE NUMBER (734) 462-4000
-----------------------------	------------------	---	---------------------------------------

Main Office Inspection Next Inspection Date: 07/2017

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine inspection of a cardiology clinic located in Livonia, Michigan. The licensee is authorized to use licensed material permitted by Title 10 Code of Federal Regulations 35.200. The licensee is staffed with one nuclear medicine technologist. The cardiology clinic performs cardiology procedures using Tc99m from the local nuclear pharmacy in the form of unit doses. The licensee obtained an outside consultant to perform program audits, instrument calibrations, and radiation safety training. The licensee is operational on Friday only. Currently, the licensee is going through ACR Accreditation and therefore, is not actively performing patient procedures. The last time patient procedures were performed was on June 1, 2012.

Performance Observations

At the time of the inspection, the technologist was unavailable due to a family emergency. The inspector reviewed selected records, toured the nuclear medicine department, and performed independent measurements. The inspector was able interview the technologist on August 6, 2012. Interviews conducted with the technologist revealed an adequate level of understanding of emergency and material handling procedures and techniques.

No violations of NRC requirements was identified.