



Serial: RNP-RA/12-0082

AUG 01 2012

Attn: Document Control Desk
 United States Nuclear Regulatory Commission
 Washington, DC 20555-0001

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
 DOCKET NO. 50-261/RENEWED LICENSE NO. DPR-23

LICENSEE EVENT REPORT NOS. 2011-001-01 and 2012-002-01
REVISIONS TO INCLUDE AND/OR CLARIFY LOSS OF SAFETY FUNCTION

Ladies and Gentlemen:

Pursuant to 10 CFR 50.73, Carolina Power and Light Company, now doing business as Progress Energy, is submitting the attached Licensee Event Report revisions. These revisions include and/or clarify the loss of safety function of the Refueling Water Storage Tank as a result of being cross-connected with the non-seismically qualified purification loop. Should you have any questions regarding this matter, please contact Mr. R. Hightower, Supervisor – Regulatory Affairs at (843) 857-1329.

This document contains no new Regulatory Commitments.

Sincerely,

Thomas S. Cosgrove
 Plant General Manager
 H. B. Robinson Steam Electric Plant, Unit No. 2

TSC/msc

- Attachments:
- I. LER 2011-001-01, Condition Prohibited by Technical Specifications When Non-Seismic System was Aligned to Refueling Water Storage Tank due to Regulatory Requirements not Adequately Incorporated in Plant Documentation
 - II. LER 2012-002-01, Unplanned LCO 3.5.4 Entry Due to RWST alignment to Purification

IE22
 NRR

c: V. McCree, NRC, Region II
A. Billoch-Colòn, NRC, NRR
NRC Resident Inspector