

**U.S. NUCLEAR REGULATORY COMMISSION**

Date: 10/16/12

**TELEPHONE CONVERSATION RECORD**

Time: 11:30 a.m.

Mail Control  
or Report No(s).

577446

License No(s). 06-08349-04

Docket No(s). 03009293

Name of Licensee: Charlotte Hungerford Hospital

Name of Participant(s): Susan Musser, PhD, Authorized Medical Physicist (AMP)

Telephone No. (860) 489-6718

Subject: Additional information for renewal

(NOTE: This will be used as the  
Documents Title in ADAMS)

I contacted the licensee to follow up on additional information provided in a deficiency response dated October 5, 2012 :

Section 2 of the attached Emergency Response Procedures for the device titled "Continuing an Interrupted Treatment" did not indicate whether the alarm conditions are analyzed to determine any causes prior to re-initiating treatment after an alarm. I asked Ms. Musser to provide informing describing how the alarm conditions will be analyzed. Ms. Musser agreed to provide this information by COB today.

**Action Required:** Issue Renewal

Document Availability:

Publicly Available

Non-Publicly Available

Non-Sensitive

Non-Sensitive Copyright

Sensitive- Proprietary

Sensitive – Privacy Act/ PII

Sensitive – Internal

Sensitive – Security-Related

Immediate Release

Normal Release Date:

Delayed Release Date:

10/24/12

SUNSI Review Completed By:

M. Abogunde

/ RA /

Document Accession #: