To: Leeds, NRR

Cys: EDO

DEDMRT

DEDR

DEDCM

Subject: FW: Nuclear plant Switchyard Reliability Date: Thursday, November 01, 2012 8:18:53 AM

AO

Wittick, OEDO

From: Tom Gurdziel [mailto:tgurdziel@twcny.rr.com]

CHAIRMAN Resource

Remsburg, Kristy; Mike, Linda; Lewis, Antoinette

Sent: Thursday, November 01, 2012 8:11 AM

To: CHAIRMAN Resource

Cc: Screnci, Diane; newal@goinfo.com; bridget.frymire@dps.ny.gov; Uldis.Vanags@state.vt.us

Subject: Nuclear plant Switchyard Reliability

Good morning,

From:

To:

Two recent events caused by winds associated with storm Sandy, (Event Number 48456 and Event Number 48453) suggest to me that addition items need to be regularly inspected at switchyards to provide increased reliable operation.

They are the need to inspect items such as lightening arrestors to see if they are still tightly connected to supports and switchyard light poles, including their anchor bolts.

It is unclear to me who actually owns the switchyards.

Thank you,

Tom Gurdziel

TEMPLATE: EDU-001

FKID1: FDD-01