

Sheet 1 of 4

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R16B006-A, Pkg F2-110 Equip. Class¹ 2

Equipment Description 600V LOAD CENTER 2D

Location: Bldg. AUX Floor El. 139 Room, Area 2335

Manufacturer, Model, Etc. (optional but recommended) _____

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A
Cannot open cabinet, anchorage is inside cabinet

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

5. Is the anchorage configuration consistent with plant documentation? Y N U N/A
(Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.)

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U
Cannot open cabinet, anchorage is inside cabinet

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

Sheet 2 of 4

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R16B006-A, Pkg F2-110 Equip. Class' 2

Equipment Description 600V LOAD CENTER 2D

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U


Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)

This package was originally signed on 8-29-12 but retyped to clarify responses on 10-24-12.

Evaluated by: *Maggie Farah* 10/24/12 Date: 8/29/12
Ron Miranda 10/24/12 8/29/12





F-2-110

F2-111

Sheet 1 of 8 ^{5 JOM}
 Status: Y N U ^{8/28/10}

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R17B001-A Equip. Class¹ 1

Equipment Description MCC 2A

Location: Bldg. AUXILIARY Floor El. 139' Room, Area 2332

Manufacturer, Model, Etc. (optional but recommended)

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A
WELDED TO FLOOR

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

5. Is the anchorage configuration consistent with plant documentation? Y N U N/A
 (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.)

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F2-111

Sheet 2 of 5
Status: Y N U
5/28/12

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R17B001-A Equip. Class 1

Equipment Description MCC 2A

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U

Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U


Comments (Additional pages may be added as necessary)

AWB IS IN FE-23

Evaluated by: S. YUAN Stephen Yuan Date: 8-28-12
P. MIKLOS Paul Miklos 8-28-12







P2-112

Sheet 1 of 8 *544*
Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R17B098-A Equip. Class¹ f

Equipment Description MCC 2CC

Location: Bldg. AUXILIARY Floor El. 155 Room, Area 2409

Manufacturer, Model, Etc. (optional but recommended) _____

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A

MCC is bolted to inverted channel welded to embed in pad. Ends can be seen easily where bolted to channel. Using camera can see other bolting of MCC to channel, OKAY

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

5. Is the anchorage configuration consistent with plant documentation? (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.) Y N U N/A

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F2-112

Sheet 2 of 3 *SM*

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No: Q2R17B098-A Equip. Class: 1

Equipment Description MCC 2CC

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U


Other Adverse Conditions

11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)


NONE


Evaluated by: Scott Warden *Scott Warden* Date: 8/29/2012
Crystal Lovelady *Crystal Lovelady* 8/29/2012



F2-11a

F2-11a





F2-113

Sheet 1 of 2
 8/24/12

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R17B002-B Equip. Class¹ 1

Equipment Description MCC 2B

Location: Bldg. Aux. Bldg Floor El. 121' Room, Area 2209

Manufacturer, Model, Etc. (optional but recommended) _____

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A
Component welded to channel welded to embedded plate. Welds inspected for cracks, corrosion and other potentially adverse seismic conditions.

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

5. Is the anchorage configuration consistent with plant documentation? Y N U N/A
 (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.)
U216585, VI

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F2-113

8/24/12

Sheet 2 of 2

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2R17B002-B Equip. Class¹ 1

Equipment Description MCC 2B

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U

Other Adverse Conditions

11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)

None

Evaluated by: P. Miktus Paul Miktus Paul Miktus 11/14/12 Date: 08-24-12

S. Yuan Stephan Yuan Paul Miktus for S. YUAN by tel com 11/14/12 08-24-12

FA-114

Sheet 1 of 8 *6/11*

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2F16T501 Equip. Class¹ 21

Equipment Description: RWST TANK

Location: Bldg. RWST Floor El. 155 Room, Area RWST

Manufacturer, Model, Etc. (optional but recommended) _____

Instructions for Completing Checklist:

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage:

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

*Dwg. D 201280 Ver. 3
Aug BB 201007 Sh. 2 Ver. 16*

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A

New CR 509918 was written to clean & coat tank hold down bolts. Eval. in CR provides acceptability for structural/seismic, OKAY.

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

Also new CR 509944 written due to drain being stopped up. small amount of water on floor, OKAY

5. Is the anchorage configuration consistent with plant documentation? (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.) Y N U N/A

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹Enter the equipment class name from Appendix B: Classes of Equipment.

F2-114

Sheet 2 of 16 M

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2F16T501 Equip. Class: 21

Equipment Description RWST TANK

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U

Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U


Comments (Additional pages may be added as necessary)


NONE


Evaluated by: Scott Wilson Pitt Wells Date: 8.30.2012

Crystal Lovelady [Signature] 8/30/2012









F2SW 2-2

Sheet 2 of 3

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31P002A Equip. Class¹ 5

Equipment Description 2A SFP PUMP

Location: Bldg: AUXILIARY Floor El. 139 Room, Area 2342

Manufacturer, Model, Etc. (optional but recommended)

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N

Dwg. D206697 Ver. 3.0

2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A

3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A

4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A

5. Is the anchorage configuration consistent with plant documentation? Y N U N/A
(Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.)

6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F2SW2-2

Sheet 2 of 3

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31P002A Equip. Class 5

Equipment Description 2A SFP PUMP

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U

Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)

NONE

Evaluated by: SCOTT WALDEN *Scott Walden* Date: 9.11.2012

Ryan Harbo *RHA* 9/11/12



F2SW2-3

Sheet 1 of 3

Status: Y N U

PARKER C. SM

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V002A Equip. Class: 0

Equipment Description 2A SFP HX INLET ISO

Location: Bldg. AUXILIARY Floor El. 155 Room, Area 2445

Manufacturer, Model, Etc. (optional but recommended)

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

- 1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N
- 2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A
IN LINE COMPONENT
- 3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A
- 4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A
- 5. Is the anchorage configuration consistent with plant documentation? (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.) Y N U N/A
IN - LINE COMPONENT
- 6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F25W2-3

Sheet 2 of 3

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V002A Equip. Class 0

Equipment Description 2A SFP HX INLET ISO

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U

Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)

NONE

Evaluated by: SCOT WALDEN Scott Walden Date: 9.11.2012

Ryan Harlos Ryan Harlos 9/11/12



F25W2-A

Sheet 1 of 84

Status: Y N U

PARKWAY 2 SFP

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V003B Equip. Class¹ 0

Equipment Description 2B SFP HX OUTLET ISO

Location: Bldg. AUXILIARY Floor El. 165 Room, Area ~~2423~~ (dress out)

Manufacturer, Model, Etc. (optional but recommended) 2423

Instructions for Completing Checklist

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N
u-line valve, no anchorage.
2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A
3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A
4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A
5. Is the anchorage configuration consistent with plant documentation? (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.) Y N U N/A
6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

¹ Enter the equipment class name from Appendix B: Classes of Equipment.

F2SW2-4

Sheet 2 of 34

Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V003B Equip. Class: 0

Equipment Description 2B SFP HX OUTLET ISO

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U


Other Adverse Conditions


11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U

Comments (Additional pages may be added as necessary)

Evaluated by: Laura MacLay Laura MacLay Date: 8/30/12

Terry A. Mullenix TERRY A. MULLENIX 8/30/2012





F28W2-5

Sheet 1 of 3
 Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V021B Equip. Class* 0

Equipment Description 2B SFP PUMP CASING VENT

Location: Bldg. AUXILIARY Floor El. 139 Room, Area 2342

Manufacturer, Model, Etc. (optional but recommended) _____

Instructions for Completing Checklist:

This checklist may be used to document the results of the Seismic Walkdown of an item of equipment on the SWEL. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

Anchorage

1. Is the anchorage configuration verification required (i.e., is the item one of the 50% of SWEL items requiring such verification)? Y N
2. Is the anchorage free of bent, broken, missing or loose hardware? Y N U N/A
3. Is the anchorage free of corrosion that is more than mild surface oxidation? Y N U N/A
4. Is the anchorage free of visible cracks in the concrete near the anchors? Y N U N/A
5. Is the anchorage configuration consistent with plant documentation? (Note: This question only applies if the item is one of the 50% for which an anchorage configuration verification is required.) Y N U N/A
6. Based on the above anchorage evaluations, is the anchorage free of potentially adverse seismic conditions? Y N U

* Enter the equipment class name from Appendix B: Classes of Equipment.

F25W2-5

Sheet 2 of 6
Status: Y N U

Seismic Walkdown Checklist (SWC)

Equipment ID No. Q2G31V021B Equip. Class' 0

Equipment Description 2B SFP PUMP CASING VENT

Interaction Effects

7. Are soft targets free from impact by nearby equipment or structures? Y N U N/A

8. Are overhead equipment, distribution systems, ceiling tiles and lighting, and masonry block walls not likely to collapse onto the equipment? Y N U N/A

9. Do attached lines have adequate flexibility to avoid damage? Y N U N/A

10. Based on the above seismic interaction evaluations, is equipment free of potentially adverse seismic interaction effects? Y N U


Other Adverse Conditions

11. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment? Y N U


Comments (Additional pages may be added as necessary)

Evaluated by: [Signature] Maggie Farah Date: 8/30/17

[Signature] Raquel Miranda 8.30.17



F2SW2-5



ATTACHMENT 4

UNIT 2 – AREA WALK-BY CHECKLISTS (AWCs)

NO. SNCF164-RPT-02

A total of 51 Area Walk-bys have been completed.
The Checklists are provided within this Attachment.

F2-3

01/21/10
Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area# 2235

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment; e.g., on the order of about 35 feet from the SWEL item.

F23

Sheet 2 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area' 2235

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train AB - Q2C11E004B

Evaluated by: P. MIKTOS *Paul Miktos* Date: 8-29-12

S. YUAN *Stephan Yuan* 8-29-12

FZ-4

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC) 77'

Location: Bldg. Aux Bldg Floor El. 83' Room, Area: 2122

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F24

2

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 83' Room, Area: 2122

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train B - Q2E11FCV0602B.

NONE

Evaluated by: Paul Miktus Date: 8-22-12
STEPHEN YUAN [Signature] 8-22-12

F2-6

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 83' Room, Area 2120

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

! If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-6

Sheet 2 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 83' Room, Area: 2120

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A


8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

B Train - MPL# Q2E11FT0605B

NONE

Evaluated by: STEPHEN YUAN Step Y Date: 8-22-12
Paul Miktus PAUL MIKTUS 8-22-12



F2-7

Sheet 1 of 3

Status: Y N U *Paul 2/24/16*

Area Walk-By Checklist (AWC)

Location: Bldg. AB Floor El. 77 Room, Area¹ 212B

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-7

Sheet 2 of 2

Status: Y N U 8/22/12

Area Walk-By Checklist (AWC)

Location: Bldg. A0 Floor El. 03 Room, Area¹ 212E

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

Fire Extinguisher mounting
determined to have no
seismic impact

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

NONE

Evaluated by: PAUL MIKLOS *Paul Miklos* Date: 8-22-12

STEPHEN YUAN *Steph* 8-22-12

~~F2-11~~ F2-11

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg: Aux Bldg Floor El. 83' Room, Area: 2128

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F-2-11

Sheet 2 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 83 Room, Area: 2128

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train B - Q2E11FIS602B, Q2E11H001B, Q2E11MOV8706B, Q2P17MOV3185B

NONE

Evaluated by: STEPHEN YOAN *[Signature]* Date: 8-22-12
PAUL MIKLOS *[Signature]* 8-22-12

P2-116
12/20/12
Camm.../12

Sheet 1 of 2
Status: Y N U *John*

Area Walk-By Checklist (AWC)

Location: Bldg: AUX Floor El. 83' Room: Area¹ 212X9

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

FOAM INSULATION OF OVERHEAD COOLER POSES NO SEISMIC IMPACT HAZARD IF IT BOMES LOOSE. BASED ON THIS WALK BY, THE INSULATION HAS NO SEISMIC FAILURE MODE AND WILL NOT BECOME DETACHED.

¹If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-12

Sheet 2 of 2

Status: Y N U

JAM 8/22/12

Area Walk-By Checklist (AWC)

Location: Bldg. AB Floor El. 77'±63' Room, Area 2129

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

NONE

RELOOKED AT 8-23-2012 SUIT WARDEN [Signature]

Evaluated by: STEPHEN YUAN [Signature] Date: 8-22-12

[Signature] PAUL MIKTOS

8-22-12

[Signature]

F2-15

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area¹ 2223

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-15

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area¹ 2223

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

Observed scaffolding near electrical box Q2P155V333B/
Scaffolding is well secured ~~to~~ and is not in the
proximity of safety related component. SWES judge that
there is no adverse seismic interaction. CR506116

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

- Train A - Q2P13HV2867C, Q2P17HV3045
- Train B - Q2E11MOV8888B, Q2E21MOV8100, Q2E21MOV8108
- Non-Train - Q2E13PT0953, Q2G24V003C

Evaluated by: [Signature] Haggie-farah Date: 8/23/12
R Miranda Ros Miranda 8/23/12

F2-23

8/28/12
2
Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 139' Room, Area¹ 2332

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F223

8/28/12
2
Sheet 2 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 139' Room, Area' 2332

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train A - Q2E16H007, Q2R17B001-A, Q2R18B030, Q2R18B032

NONE

Evaluated by: S. YUAW Stephen Yum Date: 8-28-12
P. MIKTOV Paul Mikto 8-28-12

F2-26

Sheet 1 of 34

Status: Y N U

Area Walk-By Checklist (AWC)


Location: Bldg. Aux Bldg Floor El. 100' Room, Area¹ 2172

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A



Conduit support in contaminated ledge has gap 7/16" under base plate. Determined to be adequate by engineering judgment as there are (3) 3" conduits spanning approx. 8" between adjacent supports. ~~and~~ In addition, the gravity loads are not eccentric and therefore should not cause additional lift on the b.p.

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

Scaffolding is erected in area above and next to valve. It is determined by engineering judgment to be adequate and does not pose a risk to the valve or other equipment because it is tied back to adjacent pipe supports.

TAM 8/22/2012

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F 2-26

Sheet 2 of 4

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg: Aux Bldg Floor E/L: 100' Room, Area: 2172

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A


8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train B - Q2E21LCV0115B

Evaluated by: Laura Maclay Laura Maclay Date: 8-22-12


Terry A. Mullenix TERRY A. MULLENIX 8/22/2012



F2-26

F2-26

37



F2-26

4.

F2-27

RRL

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area 2218

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

Mild rust on chiller anchorage, NO seismic concern. Surface rust only. OKAY

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-27

Sheet 2 of 2 ^{coll}

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room/Area: 2218

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A


7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train N - Q2E21LT112

NONE
WALK BY FOR ENTIRE ROOM

Evaluated by: Scott Worsow Scott Walden Date: 8.29.2012
Crystal Lovelady  8/29/2012

F2-30

Sheet 1 of 12

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 100' Room, Area¹ 2173

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F230

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxillary Floor El. 100' Room, Area: 2173

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

LM 8-22-12

B Train - MPL# Q2E16H001C, ~~Q2E21MOV8109C~~, ~~Q2E21MOV8109C~~, Q2E21MOV8109C

Evaluated by: Laura MacLay Laura MacLay Date: 8-22-12

TERRY A. W. NUMENIX / [Signature] 8/22/12

F2-32

Sheet 1 of 2

Status: Y N U *JOM 2/27/12*

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 100' Room, Area: (2163) 2175 JOM 2/27/12

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

- 1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

- 2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

- 3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

- 4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-32

Sheet 2 of 2

Status: Y N U *JAM 8/27/12*

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor: El. 100' Room, Area: 2183

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U
Yes
JAM 8/27/12

Comments (Additional pages may be added as necessary)

A Train - MPL# Q2E21MOV8130A

NONE

Evaluated by: S. YUAN *Steph* Date: 8-27-12
P. MIKUS *Paul Smith* 8-27-12

F2-36

Sheet 1 of 45

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area¹ 2184

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F236

Sheet 2 of 45

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area 2184

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

There are three sets of scaffolding in the room (381, 375, and one that could not be identified) and two ladders in the room. The scaffolding generally appears to be tied off to adjacent pipe supports and do not pose a significant seismic risk as the conduit is judged to be sufficiently supported to resist scaffolding impact forces during a seismic event. In one location, a piece of scaffolding is within 2" of a cantilevered portion of piping containing Q2E11V062B (2A RCS Loop to 2B RHR Pump HDR Drain Route) and Q2E11V062D (2A RCS Loop to 2B RHR Pump HDR Drain Route). Since the room is at a low elevation (low seismic response), the scaffold is tied back to supports, and the scaffold is between 1" and 2" away, the impact forces are deemed to be small or negligible and not a seismic risk.

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)


F2-36


Sheet 3 of 45


Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area 2184

Evaluated by: TERRY ALAN WUHENIK  Date: 8/22/2012

laura Maclay  8/22/12





F 2-37

Sheet 1 of 3
JOM
8/27/12

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area¹ 2174

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

BK
JOM

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-37

Sheet 2 of 2

Status: Y N U ² *JPH* 3/27/12

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area' 2174

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train AB - Q2E21P002B

A SMALL BUCKET IS WIRED TO PIPING ABOVE Q2E21P002B. THE LANYARD FOR THE BUCKET IS ADEQUATE TO PREVENT IT FROM BECOMING A GRAVITATIONAL MISSILE DURING A SEISMIC EVENT. THE LANYARD IS OF STOUT SS WIRE. ~~CR WAS WRITTEN TO REMOVE THE BUCKET. NO CR WAS~~

Evaluated by: P. MIKLOS *Paul Miklos* Date: 8-27-12 ^{REQUIRE}
S. YUAN *Stephen Yuan* 8-27-12 ^{PER RPH.*}

BUCKET FUNCTIONS AS A CATCH BAG IN THE PLANT.

JPH 3/27/12

F2-40

AWC

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 155' Room, Area: 2467

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-40

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 155' Room, Area 2467

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

A Train - MPL#'s Q2G31H0001B, ^{Q2G31V003B} Q2G31H001B

NONE, WALK BY FOR ENTIRE ROOM

Evaluated by: Scott Walden Date: 8.29.2012

Capital Levelady [Signature] 8/29/2012

Sheet 1 of 4

Status: Y N U

F2-42
Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 155' Room, Area: 0471 Package F2-42

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?
Inspected areas above the drop ceiling Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A
See walkdown checklist for component Q2H11NGB2504K (F2-42)

If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

Status: Y N U

F2-42

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor-El. 155' Room, Area¹ 0471 Package F2-42

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

A number of unanchored and unrestrained items were found and determined to be potential seismic interaction concerns. It was determined that this constituted a potentially adverse seismic condition and this question was therefore answered "No". These items included a rolling cart, a rolling table with a printer, a bookcase and several cabinets. See attached pages for pictures of the rolling table and bookcase. The rolling cart was found in a temporary condition and was immediately relocated. CR506338 was written to modify the table and printer and changes were immediately made. CR506373 was written to document and evaluate the remaining items with a potential to adversely impact safety related components. Some items were immediately moved and the rest were found to be stable during a seismic event based on an evaluation performed to support the CR.

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

This package was originally signed on 8-23-12 but retyped for clarity on 10-23-12.

F2-42

Sheet 3 of 4


Status: Y N U


Area Walk-By Checklist (AWC)


Location: Bldg: Auxiliary Floor El. 155' Room, Area: 0471 Package F2-42

Evaluated by: Paul Miktus *Paul Miktus* 10/23/12 Date: 08-23-12

Stephen Yuan by Telecon *Paul Miktus for* 10/23/12 08-23-12







F2049

Sheet 1 of 12

Status: Y N U **Area Walk-By Checklist (AWC)**Location: Bldg. SWIS Floor El. 188 Room, Area 72B**Instructions for Completing Checklist**

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment; e.g., on the order of about 35 feet from the SWEL item.

F2049

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. SWIS Floor El. 188 Room, Area 72B

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train B - QSW41C506B

Evaluated by: *Laura MacLay* *Laura MacLay* Date: *9/11/12*

Terry A. Mullen *Terry A. Mullen* *9/11/2012*

F2-50

Sheet 1 of 2 *2/12/20*

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121st Room, Area¹ 2227

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-50

Sheet 2 of X 2

Status: Y N U *ASD*

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 121' Room, Area¹ 2227

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

NONE, WALKBY FOR ENTIRE AREA

Evaluated by: Scott Walden *[Signature]* Date: 9.12.2012
Ryan Harlos *[Signature]* 9/12/12

F2-51

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg: Aux Bldg Floor El. 139' Room, Area: 2318

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-51

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 139' Room, Area 2318

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary).

Train A - Q2E11LQ3594A
Train B - Q2H22L001D, Q2H25L029, Q2R18B043
Non-Train - Q2R21B001D, Q2R21L001D

walkby of entire room.

Evaluated by: [Signature] Maggie Farah Date: 8/24/12
[Signature] Ros Miranda 8/29/12

F2-57

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 150' Room, Area 2462

Instructions for Completing Checklist:

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-57

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. 40 Floor El. 155' Room, Area¹ 2462

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

walkby entire room

Evaluated by: *[Signature]* Maggie Farah Date: 8/30/12

[Signature] Ron Miranda 8.30.12

F2-58

Sheet 1 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg: Aux Bldg Floor El. 127' Room: Area¹ 2241

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2.58

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg: Aux Bldg Floor El. 127' Room, Area: 2241

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train A - Q2N11HV3369C, Q2N11PV3371C, Q2N11SV3369CC, Q2N23HV3227C

Train B - Q2N11HV3370B

Train N - Q2N11PT0484

in RM. 2462 MW

WALK BY WAS FOR ENTIRE ROOM

Evaluated by: Scott Warden Scott Warden Date: 8.30.2012
Crystal Lovelady [Signature] 8/30/2012

F2-100

Sheet 1 of 2

Status: Y N U **Area Walk-By Checklist (AWC)**Location: Bldg. Aux Bldg Floor El. 100' Room, Area¹ 2190**Instructions for Completing Checklist**

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A
2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A
3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A
4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F260

Sheet 2 of 2

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Aux Bldg Floor El. 100' Room, Area' 2190

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding; lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Comments (Additional pages may be added as necessary)

Train A - Q2H22L003
Train B - Q2N23FI3229CB

NONE, AREA WALKBY INCLUDED ENTIRE ROOM,

Evaluated by: SCOTT WALDEN SWalden Date: 8.21.2012
Crystal Lovelady [Signature] 8/21/2012

F2-61

Cell 8/12/12

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 100' Room, Area¹ 2194

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

Minor rust on bolts for Exhaust Fan, N2V475022,
Judged to be acceptable. photo

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-61

8/23/12

Sheet 2 of 3-4

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 100' Room, Area: 2194

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U


Comments (Additional pages may be added as necessary)

B Train - MPL# Q2N23FT3229B

NONE, AREA WALKBY INCLUDED ENTIRE ROOM

Evaluated by: SCOTT WALDEN [Signature] Date: 8.21.2012


Crystal Lorelady [Signature] 8/21/2012



Run Area: 2194

F2-61

Sheet 4 of 4



F2-57

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. Auxiliary Floor El. 150' Room, Area 2462

Instructions for Completing Checklist:

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment, e.g., on the order of about 35 feet from the SWEL item.

F2-6A

Sheet 1 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. AUXILIARY Floor El. 100 Room, Area: 2191

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

1. Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Y N U N/A

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? Y N U N/A

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Y N U N/A

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Y N U N/A

¹ If the room in which the SWEL item is located is very large (e.g., Turbine Hall), the area selected should be described. This selected area should be based on judgment; e.g., on the order of about 35 feet from the SWEL item.

F2-64

Sheet 2 of 3

Status: Y N U

Area Walk-By Checklist (AWC)

Location: Bldg. AUXILIARY Floor El. 100 Room, Area: 2191

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area? Y N U N/A

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area? Y N U N/A

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)? Y N U N/A

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? Y N U

Chain hangs from overhead to operate valve. Mass is so small that any impact would Not be of any seismic consequences, OK.

Comments (Additional pages may be added as necessary)
MASS OF Chain smaller than all other items.

NONE -
WALK BY for entire Area

Evaluated by: SCOTT WALDEN Scott Walden Date: 8-28-2012

TAYLOR YOUNGBLOOM Taylor Youngblood 8-28-2012

