



PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

G/Gmax and Material Damping
Curves for Soil Layers 9A and 9B

FIGURE 2.5.2-80 Rev 0