

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Amercan Renolit Corporation
1207 E. Lincolnway
Laporte, IN46350-3987

REPORT NUMBER(S) 13-01

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-18733

4. LICENSE NUMBER(S)

13-24638-01

5. DATE(S) OF INSPECTION

7/29 through 8/7/2013

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer		8/5/13
BRANCH CHIEF	Aaron T. McCraw		8/8/13

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Amercan Renolit Corporation 1207 E. Lincolnway Laporte, IN46350-3987 REPORT NUMBER(S) 13-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
-------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------

3. DOCKET NUMBER(S) 030-18733	4. LICENSE NUMBER(S) 13-24638-01	5. DATE(S) OF INSPECTION 7/29 through 8/7/2013
--------------------------------------	-----------------------------------------	-------------------------------------------------------

6. INSPECTION PROCEDURES USED IP 87124	7. INSPECTION FOCUS AREAS 03.01 through 03.07
-----------------------------------------------	------------------------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3120	2. PRIORITY 5	3. LICENSEE CONTACT Timothy D. Jones	4. TELEPHONE NUMBER (219) 324-6886
--------------------------------	----------------------	---------------------------------------------	-------------------------------------------

Main Office Inspection Next Inspection Date: 7/29/2013

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is a engineering firm that employs 160 individuals. The licensee possesses four specifically licensed BetaControl Model MK 1.0 fixed gauges used to determine the thickness of plastic coatings. Currently, one individual is involved with use and oversight of the devices which is the RSO. Inventories and shutter checks are performed at required at six-month frequencies.

The licensee is not authorized to remove and/or relocate gauges, according to the RSO, gauges are relocated, removed, etc. by the manufacturer. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer.

Performance Observations

The plant facility was toured and approximately four gauges were observed in conjunction with the licensee's current inventory. The RSO demonstrated survey techniques used if/when a gauge is relocated. Proper lock-out and leak test procedures were also adequately described. Interviews conducted with plant workers revealed that under no circumstances would a vessel be entered without RSO supervision of lock-out/tag-out procedures. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

The inspector reviewed the following previous violations: failure to maintain constant surveillance and control of Licensed material (10CFR20.1802); Condition 14 of NRC License 13-24638-01 requiring removal of licensed material by persons specifically licensed by the Commission; Condition 11 of NRC License 13-24638-01 states a specific individual shall be RSO and this individual left the company.

The inspector had no findings in these areas.