

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Arcelormittal USA, LLC 3210 Watling Street East Chicago, IN 46312</p> <p>REPORT NUMBER(S) 2013-002</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>	
<p>3. DOCKET NUMBER(S)</p> <p>030-35880 (previously 030-04353)</p>	<p>4. LICENSE NUMBER(S)</p> <p>13-32359-01 (previously 13-03086-03)</p>	<p>5. DATE(S) OF INSPECTION</p> <p>8/12/2013</p>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ryan Craffey		8/19/13
BRANCH CHIEF	Aaron McCraw		8/19/13

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Arcelormittal USA, LLC 3210 Watling Street East Chicago, IN 46312 REPORT NUMBER(S) 2013-002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-35880 (previously 030-04353)	4. LICENSE NUMBER(S) 13-32359-01 (previously 13-03086-03)	5. DATE(S) OF INSPECTION 8/12/2013
---	--	---

6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03120	2. PRIORITY 5	3. LICENSEE CONTACT Scott Bush - RSO	4. TELEPHONE NUMBER (219) 399-6498
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: No change

Field Office Inspection 3300 Dickey Road, East Chicago, IN

Temporary Job Site Inspection

PROGRAM SCOPE

This follow-up inspection was limited to assessing the effectiveness of the licensee's corrective actions to prevent violations similar to one identified by an NRC special inspection conducted on October 10, 2012. Specifically, the inspector assessed the licensee's corrective actions to prevent the unauthorized removal of or access to licensed materials that are stored in controlled or unrestricted areas at its Long Carbon Mill in East Chicago, Indiana.

PERFORMANCE OBSERVATIONS

The inspector interviewed the RSO, the environmental manager of the Long Carbon Mill and the individual in the mill's shipping and receiving department who originally took receipt of the material that had been left unsecured. The inspector verified that the RSO understood the root cause of the violation - a miscommunication between himself and the outgoing RSO - and verified that the Long Carbon Mill staff were knowledgeable of the licensee's procedures for receipt of radioactive material.

The inspector reviewed the licensee's training records, which demonstrated that all shipping and receiving staff had been provided hazardous materials retraining in November 2012. The licensee indicated that it would now require this refresher training at annual intervals. The inspector also reviewed the licensee's procedures for receipt of radioactive material, in addition to the records for two shipments of radioactive materials received in May 2013. Through this review and through further discussions with the RSO, the inspector determined that these shipments of material had been received in accordance with the licensee's procedures and that the material had been adequately stored prior to installation.

Based upon these observations, the NRC has determined that the licensee implemented corrective actions to prevent violations similar to those that were identified during the October 2012 inspection.