

U.S. NUCLEAR REGULATORY COMMISSION

Date: 8/20/2013

TELEPHONE CONVERSATION RECORDMail Control
or Report No(s).

581437

License No(s).

STB-1530

Docket No(s).

04008974

Name of Licensee:

Budney Overhaul & Repair, LTD

Name of Participant(s):David Durkee, Consultant (Radcor, LLC)
Dennis Lawyer, R1, DNMS**Telephone No.**

860-608-2083

Subject:

RAI, Survey questions

(NOTE: This will be used as the
Documents Title in ADAMS)

I asked Mr. Durkee about the background readings taken and if the concrete was poured at the same time as the main area floor. He believed that they were built at two different times but that was best he could use that was similar and yet not affected by the material. I asked if he used beta and alpha counting on the detector, and he said that was how he counted everything. I did discuss that I had evaluated the results using 0.25 self-absorption factor due to the alpha component. I also asked if the facility was painted and he said that it wasn't but the floor was coated prior to starting operations.

Action Required: None**Document Availability:** Publicly Available Non-Publicly Available Non-Sensitive
 Sensitive – Privacy Act/ PII
 Immediate Release Non-Sensitive Copyright
 Sensitive – Internal
Normal Release Date: Sensitive- Proprietary
 Sensitive – Security-Related
Delayed Release Date:SUNSI Review Completed By: Dennis Lawyer / RA /