

# LICENSEE EVENT REPORT

LER 77-02

CONTROL BLOCK: 

--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 

01	C	A	S	O	S	I
----	---	---	---	---	---	---

 LICENSE NUMBER: 

00	00	-	00	00	00	00	-	00	00
----	----	---	----	----	----	----	---	----	----

 LICENSE TYPE: 

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE: 

0	1
---	---

CATEGORY: 

01	CONT
----	------

 REPORT TYPE: 

P	0
---	---

 REPORT SOURCE: 

P	L
---	---

 DOCKET NUMBER: 

0	5	0	-	0	2	0	6
---	---	---	---	---	---	---	---

 EVENT DATE: 

0	1	1	7	7	7
---	---	---	---	---	---

 REPORT DATE: 

0	1	3	1	7	7
---	---	---	---	---	---

### EVENT DESCRIPTION

02 | During a routine visual inspection of the containment spray system, an apparent  
03 | through-wall flaw was located in the base metal of the refueling water pump discharge  
04 | line. This report is nonrepetitive. Defective pipe will be replaced (77-02).  
05 |  
06 |

SYSTEM CODE: 

S	F
---	---

 CAUSE CODE: 

E
---

 COMPONENT CODE: 

P	I	P	E	X	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

A
---

 COMPONENT MANUFACTURER: 

B	1	3	0
---	---	---	---

 VIOLATION: 

N
---

### CAUSE DESCRIPTION

08 | The SA312, TP304, 6 inch schedule 10s pipe failed because of sensitization to inter-  
09 | granular stress corrosion, probably due to improper annealing during initial  
10 | fabrication.

FACILITY STATUS: 

G
---

 % POWER: 

0	0	0
---	---	---

 OTHER STATUS: 

NA
----

 METHOD OF DISCOVERY: 

B
---

 DISCOVERY DESCRIPTION: 

NA
----

  
FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

NA
----

 LOCATION OF RELEASE: 

NA
----

PERSONNEL EXPOSURES  
NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

NA
----

PERSONNEL INJURIES  
NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

NA
----

OFFSITE CONSEQUENCES  
NA

LOSS OR DAMAGE TO FACILITY  
TYPE: 

Z
---

 DESCRIPTION: 

NA
----

PUBLICITY  
NA

ADDITIONAL FACTORS  
NA

18 | 8103060062

NAME: H. L. Ottoson PHONE: (714) 492-7700