

LICENSEE EVENT REPORT

Regulatory Docket File LER (77-03)

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 C A S O S I			LICENSE NUMBER 00 - 000000 - 00										LICENSE TYPE 4 1 1 1 1			EVENT TYPE 0 3	
CON'T 01		CATEGORY P O	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 050 - 0206					EVENT DATE 012477			REPORT DATE 021477				

EVENT DESCRIPTION

02 DURING A ROUTINE INSPECTION OF THE AREA, A LEAK WAS OBSERVED

03 IN THE EAST RESIDUAL HEAT REMOVAL PUMP COOLING WATER RETURN

04 LINE. THE LEAK WAS THE RESULT OF CONSTRUCTION PERSONNEL

05 MISTAKENLY CUTTING INTO AN INCORRECT LINE. REDUNDANT SYSTEMS

06 WERE AVAILABLE. THE EVENT IS NON REPETITIVE (LER 77-03)

SYSTEM CODE 07 C F	CAUSE CODE A	COMPONENT CODE P I P E X X	PRIME COMPONENT SUPPLIER A	COMPONENT MANUFACTURER B 1 3 0	VIOLATION N
-----------------------	-----------------	-------------------------------	-------------------------------	-----------------------------------	----------------

CAUSE DESCRIPTION

08 THE CAUSE OF THIS EVENT WAS PERSONNEL ERROR. A TEMPORARY

09 WELD REPAIR WAS MADE TO STOP THE LEAK. A PERMANENT REPAIR WAS

10 MADE AT A LATER TIME. WORK PROCEDURES WERE REVISED TO INCREASE JOB AWARENESS.

FACILITY STATUS 11 G	% POWER 000	OTHER STATUS NA	METHOD OF DISCOVERY B	DISCOVERY DESCRIPTION NA
FORM OF ACTIVITY RELEASED 12 Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA	

PERSONNEL EXPOSURES

NUMBER 13 000	TYPE Z	DESCRIPTION NA
------------------	-----------	-------------------

PERSONNEL INJURIES

NUMBER 14 000	DESCRIPTION NA
------------------	-------------------

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z	DESCRIPTION NA
--------------	-------------------

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19 8103060082

NAME: H. H. O'Hanlon/REM

PHONE: 714/492-7700