REGULATEY, INFORMATION DISTRIBUTION STEM (RIDS)

. . .

in the second

ACCESSI FACIL: AUTH. BASKIN RECIP MIRAGL	ON NBR: 8201 50-361: Sah 50-362: Sah NAME , K. P. NAME NAME IA, F.	210211. Dhoifine Nui Dhoifine Nui AUTHOR Al Southern I RECIPTENI Llicens	DOCLDAT cileariSt cileariSt FFILIATI Calliforn TIAFFILII ing Bran	E: B2 ation DN ia Ed ATION ch 3	/01/13 / Unit / Unit ison Co	NOTARIZE 2, Southe 3, Southe	D: NO rn:Californ: rn:Californ:	DDCKET: # 05000361; 05000362;
SUBJEC	T: Discusse cooiling confiden requirem	s indicate ICCI static ce in inte ents can b	ors for on proce erdm ICC de insta	detec dures i sys i led	tion of & trai until s during	inadequa ning that ys meetin first ref	te core justify g NUREG=0737 ueling outag	7) 30 • A
DISTRI TITLE:	BUTION CODE PSAR/FSAR	: 30015 (AMDITS and	CDPIES R Related	ECEIV Corr	ED:LITR esponde	L'ENCLI _ nce	SIZE:	2
NOTES:	Li Chandl'er:	allı FISAR	s ER: ame	nds.1	cy:J H	anchett(R	egion V).	05000361
	D Scaletti: L[Chandler: D Scaletti:	1: cy and a ann FSAR 1: cy ann a	envirtin 3 ER ame envirtin	nds.1. fo.	cy:J:H	anchett(R	egion V).	05000362)
	RECIPIE	NT (COPIES		RECIP	IENT	COPIES	
ACTION:	ID CODE/ A/D LICEN	NAMEL I SNGI	LITITR ENC 1. 0	: L (ID COD Liici Br	EVNAME: #3. BCI		
	LIC BR #3	LIA	1. 0		ROOD, H.	01	1 1	
INTERNAL	ELD IE/DEP/EP	08: 35	1: 0 1: 1	•	IE IEVDEP/	06 EPLB 36	3 3. 3 3.	
	MPA	a: t3.	1 0		NRR/DE/	CEB: 14/		
	NRR/DE/HG	2B/ 30	5 , 2		NRR/DE/	MEB 18	1 1	
	NRRIDEVMT	EB(17-	1. 1	. i	NRRIDEI	QAB 21.	1 1	
	NRRIDEVSA	31 24'		i	NRR/DE/	SEB 25		
	NER/DHEB/	17204V				S/LHD SC. S/Pitra20	1 1	
	NRR/DSI/A	EB 25	1 1		NRR/DSI	/458 27	1 1	
	NRR/DSI/C	PB 1.0	1 1	i	NRR/DSI	/CSBI 09	1 1	
	NRR/DSI/E	ISB 12.	1. 1		NRR/DSI	/IC/53+16	1 1	
	NRR/DSI/P	SB 19	1. 1		NRR/DSI	/RAB(22)	1 1	
(RES FILE	0.4	1 1 12 1		NKK/USI	/ LGOK - 30°	1 1	
EXTERNAL	ACRS	41.	15 16	, 1	BNLICAMD	TS ONLY)	1 1	
	FEMA-REP	DILVE 39	1) 1	. 1	LPDR	03	1 1	
	NRC POR	021	1 1	i	NSIC	0.5	1 1	
	NITO .		1. 1					

TOTAL NUMBER OF COPIES REQUIRED: LITTR 53 ENCL 58

Southern California Edison Company

P. O. BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN MANAGER OF NUCLEAR ENGINEERING, SAFETY, AND LICENSING

January 13, 1982

Director, Office of Nuclear Reactor Regulation Attention: Mr. Frank Miraglia, Branch Chief Licensing Branch No. 3 U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Gentlemen:



Subject: Docket Nos. 50-361 and 50-362 San Onofre Nuclear Generating Station Units 2 and 3

In response to questions asked by NRC management during the November 18, 1981 and December 3, 1981 meetings relative to the subject of instrumentation for Inadequate Core Cooling (ICC), SCE's letter of December 16, 1981 reiterated SCE's position that the interim ICC system coupled with station operating instruction (OIs) and training provides a high degree of confidence that ICC will be detected and mitigated and that the interim system is sufficient for station operation during the first fuel cycle until the final ICC system can be implemented. The final ICC system will meet the requirements of Item II.F.2 of NUREG-0737 and will be implemented during the first refueling outage for San Onofre Unit 2, or the first unscheduled outage of sufficient duration following delivery of all necessary material/equipment, rather than the January 1, 1982 NRC requirement.

As part of a response to a specific question asked by Mr. Mattson, the December 16, 1981 letter also indicated that in addition to the 56 Core Exit Thermocouples, other multiple and diverse indicators could be used to detect ICC. As an example, the letter indicated the following multiple and diverse indicators are also considered for the detection of ICC during a Loss of Primary Inventory Event:

> RCS Subcooled Margin Pressurizer Pressure Steam Generator Δ P Reactor Coolant Pump Motor Amps RCS Temperature (hot and cold leg) Core Exit Thermocouples High Pressure Safety Injection Flow

Pool S.10

8201210211

Mr. Frank Miraglia

During a recent telephone discussion, the NRC (Mr. F. Miraglia) indicated that the availability of the Reactor Coolant Pump Motor Amps as an indicator for the detection of ICC was questionable since the Reactor Coolant Pumps would be tripped during Loss of Primary Inventory Events. It should be noted that the parameters listed above are indicators that could be considered in the determination of ICC during all loss of primary inventory events. The procedure requires trending those indicators that could be available for the particular event in progress; while it is correct that the RCPs will be tripped when RCS pressure falls below the SIAS initiation setpoint, there are events where the pressure decrease may be relatively slow (thus providing information which could be used in detecting the onset of ICC until the RCPs are tripped) or events where re-start of the RCPs is allowed. Therefore, the Reactor Coolant Pump Motor Amps indication provides meaningful information in the detection of ICC or determination of the onset of ICC if the RCPs have not been tripped.

-2-

If you have any questions or comments concerning this information, please contact me.

Very truly yours,

2 P Bashin