


Southern California Edison Company



P. O. BOX 800


2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

A. ARENAL
VICE PRESIDENT

TELEPHONE
213-572-1476

October 9, 1979



U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Docket No. 50-206
San Onofre Unit 1

Dear Sir:

IE Inspection Report
No. 50-206/79-12


The subject IE Inspection Report was forwarded by letter dated September 21, 1979 from Mr. J. L. Crews of your office. Appendix A to that letter was a Notice of Violation concerning failure to calibrate certain pressure gages and omissions in Station Order S-A-112, Listing of Equipment Subject to the Quality Assurance Program. This letter provides our response to that Notice of Violation pursuant to 10 CFR 2.201.

1. Cause of the Violations

- A) Station Order S-E-115, Requirements for the Calibration and Control of Measuring and Test Instrumentation, had been revised in April of 1978 increasing the frequency of calibration for the Roylyn pressure gages from 2 years to 6 months. However, measures to insure that the Roylyn pressure gages were actually calibrated at the increased frequency were not taken.
- B) The items missing from Station Order S-A-112 were apparently removed by a clerical error in a previous revision of the Station Order.

7911 090

CCP
149
79-766



2. Steps Taken to Correct the Violations

- A) The 4 Roylyn pressure gages were calibrated in accordance with S-E-115 and were found to be in calibration. Consequently, the calibration of instruments calibrated to the Roylyn gages is satisfactory and not in question.
- B) A temporary operating memorandum has been issued to include the missing items in S-A-112.

3. Steps Taken to Prevent Recurrence

- A) The dated file card system which insures that gages and instruments are calibrated as required has been corrected to insure that the Roylyn pressure gages are calibrated every 6 months.
- B) Station Order S-A-112 will be corrected to include the missing items. Revision of the order will be accomplished by November 24, 1979.

The above corrective actions should eliminate the areas of concern noted in the subject report.

Should you have any questions concerning this response, please contact me.

Sincerely,

A. Arnold