REGULATORY FORMATION DISTRIBUTION SY EM (RIDS)

ACCESSION NBR:8002190497 DOC.DATE: 80/02/13 NOTARIZED: NO DOCKET # FACIL:50-206 San Onofre Nuclear Station, Unit 1, Southern Californ 05000206

AUTH.NAME AUTHOR

AUTHOR AFFILIATION

CURRAN, J.M.

Southern California Edison Co.

RECIP.NAME RECIPIENT AFFILIATION

Region 5, San Francisco, Office of the Director

SUBJECT: LER 80-004/03L-0:on 800119 during normal operation,B feedwater flow indication increased about 15% above actual flow.Caused by missing segments in flow straightener indicated by radiograph.Straightener was replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR __ ENCL __ SIZE: _2 + ______
TITLE: Incident Reports

NOTES: ICH: J. SHAPAKER, C. HOFMAYER.

	i .			*		
	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
ACTION:	05 BC ORB #2	4	4			
•						
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 18E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	į	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACDENT ANLYS	1	1
	29 AUX SYS BR	1	1	AD/ORP-DOR	1	1
	AEOD	1	1	DOUG MAY-TERA	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	R IRELAND	3	3	•		
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
more than the first man of	29 ACRS	16	16	,		-
	***		-			

FEB 2 1 1980

1

AO/I

TOTAL NUMBER OF COPIES REQUIRED: LTTR 52 ENCL 52