Status: Y N U

Area Walk-By Checklist (AWC)

Loca	ntion (Bldg, Elev, Room/Area): Area 07 - CON2, 612, 70			
Instructions for Completing Checklist This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.				
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes		
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes		
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes		
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?	Yes		
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes		
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes		
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes		

Location (Bldg, Elev, Room/Area):

Area 07 - CON2, 612, 70

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Amoisay M. Mostes
(Allend).

Lindsay M. Yates Date: 08/15/2013

Neda Stoeva

08/15/2013



P9120063





P9120064



Location (Bldg, Elev, Room/Area): P9120065

Area 07 - CON2, 612, 70 P9120066









P9120069



P9120070



P9120071



P9120072

Location (Bldg, Elev, Room/Area): Area 07 - CON2, 612, 70




P9120073



P9120075



P9120074



P9120076

Location (Bldg, Elev, Room/Area):

Area 07 - CON2, 612, 70



P9120077



P9120078



P9120079



P9120080

P9120085

Area 07 - CON2, 612, 70 Location (Bldg, Elev, Room/Area): P9120082 P9120081 P9120083 P9120084

P9120086

P9120091

Area 07 - CON2, 612, 70 Location (Bldg, Elev, Room/Area): P9120087 P9120088 P9120089 P9120090

P9120092

P9120097

Location (Bldg, Elev, Room/Area): Area 07 - CON2, 612, 70 P9120093 P9120094 P9120096 P9120095

P9120098

P9120103

Location (Bldg, Elev, Room/Area): Area 07 - CON2, 612, 70 P9120100 P9120099 P9120101 P9120102


P9120104

Location (Bldg, Elev, Room/Area):

Area 07 - CON2, 612, 70



P9120105



P9120106



P9120107

Status: Y N U

Area Walk-By Checklist (AWC)

Location (Bldg, Elev, Room/Area):

Area 08 - AB2, 609, 140

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

 Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?
 Equipment anchorage is internal, could not see Not Applicable

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions?

Not Applicable

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?

Yes

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?

Yes

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?

Fire protection piping - CO2 system. Rod hung.

Yes

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?

Yes

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?

Yes

Location (Bldg, Elev, Room/Area): Area 08 - AB2, 609, 140

Hook with magnet on side of SG - will not be a seismic hazard due to strength of magnet.

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Harry H. June

- George G Thomas

Date: 08/15/2013


Samantha Justice Mindsay M. Motes

per teleconference withSamantha Justice on 8/7/2013

08/15/2013









P9120161



Location (Bldg, Elev, Room/Area):

Area 08 - AB2, 609, 140 P9120173

P9120172



P9120174



P9120175



P9120176



P9120177

Location (Bldg, Elev, Room/Area):


Area 08 - AB2, 609, 140



P9120178



P9120179



P9120180



P9120181

Location (Bldg, Elev, Room/Area): Area 08 - AB2, 609, 140





P9120182

P9120183

Location (Bldg, Elev, Room/Area):

Area 08 - AB2, 609, 140





P9120185









P9120187

Location (Bldg, Elev, Room/Area): Area 08 - AB2, 609, 140









P9120190



P9120191

Status: | Y | N U

Area Walk-By Checklist (AWC)

shielding)?

Location (Bldg, Elev, Room/Area): Area 10 - AB2, 621, 10 - BY 2MRV-243 & 2-FFI-240 Instructions for Completing Checklist This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? 2. Does anchorage of equipment in the area appear to be free of Yes significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? 4. Does it appear that the area is free of potentially adverse seismic Yes spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? Yes 7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead

Location (Bldg, Elev, Room/Area): Area 10 - AB2, 621, 10 - BY 2MRV-243 & 2-FFI-240

Ladder OK laid flat underneath pipes away from equipment

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Hanny M. down George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12




P9100228



P9100229

Location (Bldg, Elev, Room/Area):

Area 10 - AB2, 621, 10 - BY 2MRV-243 & 2-FFI-240





P9100231





P9100232



P9100233

Location (Bldg, Elev, Room/Area):

Area 10 - AB2, 621, 10 - BY 2MRV-243 & 2-FFI-240




P9100234



P9100235



P9100236



P9100237




P9100238



P9100239

Location (Bldg, Elev, Room/Area):

Area 10 - AB2, 621, 10 - BY 2MRV-243 & 2-FFI-240



P9100240

Status:	Υ	N	U
Otatus.		14	U

shielding)?

Location (Bldg, Elev, Room/Area): Area 11 - AB2, 612, 12 - BY 2-NPS-111 **Instructions for Completing Checklist** This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? 2. Does anchorage of equipment in the area appear to be free of Yes significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? 4. Does it appear that the area is free of potentially adverse seismic Yes spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? 7. Does it appear that the area is free of potentially adverse seismic Yes interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead

Location (Bldg, Elev, Room/Area): Area 11 - AB2, 612, 12 - BY 2-NPS-111

Ramp piece not tied to anything by 2-ECR-23 - pressurized gas bottles infront of ramp, but ramp leans up against the bottle supports as found. Judged acceptable by Seismic Walkdown Engineers (SWEs) because it could not have an unacceptable interaction with a safety related component. AR 2012-11363 issued to address housekeeping issue.

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

11. George G Thomas Date: 08/15/2013

Neda Stoeva

08/15/2013







P9100249

Location (Bldg, Elev, Room/Area): Area 11 - AB2, 612, 12 - BY 2-NPS-111







P9100252



P9100251



P9100253

Location (Bldg, Elev, Room/Area): Area 11 - AB2, 612, 12 - BY 2-NPS-111



P9100254



P9100255

Location (Bldg, Elev, Room/Area):




P9100256



P9100257

Location (Bldg, Elev, Room/Area):

Area 11 - AB2, 612, 12 - BY 2-NPS-111



P9100258



P9100259

Location (Bldg, Elev, Room/Area):

Area 11 - AB2, 612, 12 - BY 2-NPS-111



P9100260



P9100261

Location (Bldg, Elev, Room/Area): Area 11 - AB2, 612, 12 - BY 2-NPS-111



P9100262

Status: Y N U

Area Walk-By Checklist (AWC)

Loca	tion (Bldg, Elev, Room/Area): Area 13 - AB2, 609, 4				
Instru	ctions for Completing Checklist				
This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.					
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Braces for pipe support seem like missing 2 bottom bolts each, but have welds at bottoms instead	Yes			
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes			
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes			
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?	Yes			
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes			
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes			
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes			

Location (Bldg, Elev, Room/Area):

Area 13 - AB2, 609, 4

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

George G Thomas Date: 10/18/12

Neda Stoeva

10/18/12



P9180993



P9180994

Location (Bldg, Elev, Room/Area):

Area 13 - AB2, 609, 4



P9180995



P9180996



P9181001



P9181002



Location (Bldg, Elev, Room/Area):

Area 13 - AB2, 609, 4



P9181010



P9181011



P9181012



P9181013

Location (Bldg, Elev, Room/Area):



P9181014



P9181015

Location (Bldg, Elev, Room/Area): Area 13 - AB2, 609, 4



P9181016

Status: Y N U

Area Walk-By Checklist (AWC)

Loca	ation (Bldg, Elev, Room/Area): Area 14 - AB2, 587, 40	
Instru	ctions for Completing Checklist	
The sp	hecklist may be used to document the results of the Area Walk-By near one or more SWE bace below each of the following questions may be used to record the results of judgment ps. Additional space is provided at the end of this checklist for documenting other comme	s and
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Block wall with grate - OK per DWG 12-4026, Wall W-5.	Yes
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes

Location (Bldg, Elev, Room/Area):

Area 14 - AB2, 587, 40

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Hanny M. Down George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12



P9180765



P9180766

Location (Bldg, Elev, Room/Area):



P9180767





P9180768



P9180769

Status: Y N U

Area Walk-By Checklist (AWC)

Location (Bldg, Elev, Room/Area):

Area 15 - AB2, 587, 41

Instructions for Completing Checklist

This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.

 Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)? No

No nut on 1 of 4 bolts supporting 2-CS-301W - AR 2012-11780 was issued to address this issue.

2. Does anchorage of equipment in the area appear to be free of significant degraded conditions?

Yes

Abandoned U-bolt partially cut above pump 2-PP-50W. Judged not to be a seismic vulnerability. AR 2012-11691 issued.

3. Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?

Yes

4. Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?
Block wall with grate - OK per DWG 12-4026, Wall W-6.

Yes

5. Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?

Yes

6. Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?

Yes

7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?

Yes

Location (Bldg, Elev, Room/Area):

Area 15 - AB2, 587, 41

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Han M. Beorge G Thomas

Date: 08/15/2013

Neda Stoeva

08/15/2013









P9180748



D-282

Location (Bldg, Elev, Room/Area): P9180749

Area 15 - AB2, 587, 41 P9180750





P9180752







P9180754

Location (Bldg, Elev, Room/Area):

Area 15 - AB2, 587, 41



P9180755



P9180757



P9180756



P9180758

Status: Y N U

Area Walk-By Checklist (AWC)

Loca	tion (Bldg, Elev, Room/Area): Area 16 - AB2, 587, 43	
Instru	ctions for Completing Checklist	
The sp	necklist may be used to document the results of the Area Walk-By near one or more SWEL ace below each of the following questions may be used to record the results of judgments s. Additional space is provided at the end of this checklist for documenting other comment	and
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions? Pipe support downstream of 2-SI-115S is slightly warped by bottom left bolt. This is shown in Picture P9180885 below. Support warping likely due to heat from welding when installing support. Support capable of performing its function.	Yes
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes
. 4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?	Yes
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes

Location (Bldg, Elev, Room/Area):

Area 16 - AB2, 587, 43

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

George G Thomas

Date: 08/15/2013

Neda Stoeva

08/15/2013







P9180880

Location (Bldg, Elev, Room/Area):

Area 16 - AB2, 587, 43



P9180881





P9180883



P9180884

Location (Bldg, Elev, Room/Area): Area 16 - AB2, 587, 43







P9180886

Status:	1/	N.	
Status:	Y	l IN	U

Loca	ation (Bldg, Elev, Room/Area): Area 17 - AB2, 573, 52			
	ctions for Completing Checklist			
The s	This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.			
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes		
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes		
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes		
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Block wall - OK per DWG 12-4025, Wall W-22.	Yes		
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes		
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes		
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shiolding)?	Yes		

Location (Bldg, Elev, Room/Area):

Area 17 - AB2, 573, 52

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Han M. George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12








P9180809

Location (Bldg, Elev, Room/Area):

Area 17 - AB2, 573, 52



P9180810





P9180814



P9180811



P9180813



P9180815

Location (Bldg, Elev, Room/Area):



P9180816

Area 17 - AB2, 573, 52



P9180817

Location (Bldg, Elev, Room/Area): Area 17 - AB2, 573, 52



P9180818



P9180819

Status: Y N U

Area Walk-By Checklist (AWC)

Location (Bldg, Elev, Room/Area): Area 18 - AB2, 573, 55 **Instructions for Completing Checklist** This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? 2. Does anchorage of equipment in the area appear to be free of Yes significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? 4. Does it appear that the area is free of potentially adverse seismic Yes spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Block wall - OK per DWG 12-4025, Wall W-24. 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? 7. Does it appear that the area is free of potentially adverse seismic Yes interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?

Location (Bldg, Elev, Room/Area):

Area 18 - AB2, 573, 55

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Hanny M. danse George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12



P9180865



P9180866

Location (Bldg, Elev, Room/Area):



P9180867



P9180868

Location (Bldg, Elev, Room/Area):

Area 18 - AB2, 573, 55



P9180869



P9180870

Status:	Υ	N	u
Otatus.	_	1.4	U

Loca	ation (Bldg, Elev, Room/Area): Area 19 - AB2, 609, 6	
Instru	ctions for Completing Checklist	
The sp	necklist may be used to document the results of the Area Walk-By near one or more SWE bace below each of the following questions may be used to record the results of judgments s. Additional space is provided at the end of this checklist for documenting other commer	s and
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?	Yes
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes

Location (Bldg, Elev, Room/Area):

Area 19 - AB2, 609, 6

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area? 2-ICM-321 outlet downstream pipe support bottom left corner bolt spalled concrete - AR#0115039 and WO#55060450, previously evaluated for Use-As-Is.

Yes

Comments


Evaluated by:

Han M. Dock George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12







P9181151

Location (Bldg, Elev, Room/Area): Area 19 - AB2, 609, 6



P9181152




P9181154



P9181156



P9181153



P9181155



P9181157

Location (Bldg, Elev, Room/Area): Area 19 - AB2, 609, 6







P9181159



P9181160



P9181161

Location (Bldg, Elev, Room/Area):



P9181162

Area 19 - AB2, 609, 6



P9181163

Location (Bldg, Elev, Room/Area): Area 19 - AB2, 609, 6



P9181164

Status: Y N U

Area Walk-By Checklist (AWC)

Area 21 - AB2, 633, 633 BY 2-CFI -429 and 2-WMO-716

and 2-WMO-718 Location (Bldg, Elev, Room/Area): **Instructions for Completing Checklist** This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? 2. Does anchorage of equipment in the area appear to be free of Yes significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? 4. Does it appear that the area is free of potentially adverse seismic No spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Fire extinguishers on short hooks by General area between 2-WMO-715 and 2-CFI-429 - AR 2012-11669 was issued. 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? 7. Does it appear that the area is free of potentially adverse seismic Yes

interactions associated with housekeeping practices, storage of

shielding)?

portable equipment, and temporary installations (e.g., scaffolding, lead

Area 21 - AB2, 633, 633 BY 2-CFI -429 and 2-WMO-716 and 2-WMO-718

Location (Bldg, Elev, Room/Area):

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:


Many M. Date: 08/15/13

Neda Stoeva

08/15/13



P9100110



P9100111


Area 21 - AB2, 633, 633 BY 2-CFI -429 and 2-WMO-716 and 2-WMO-718







P9100113



P9100114



P9100115

Area 21 - AB2, 633, 633 BY 2-CFI -429 and 2-WMO-716 and 2-WMO-718














P9100148

Area 21 - AB2, 633, 633 BY 2-CFI -429 and 2-WMO-716 and 2-WMO-718





P9100149



P9100151



P9100150

Status: Y N U

Area Walk-By Checklist (AWC)

shielding)?

Location (Bldg, Elev, Room/Area): Area 22 - AB2, 633, 8 **Instructions for Completing Checklist** This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? Yes 2. Does anchorage of equipment in the area appear to be free of significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? Cable trays lightly loaded 4. Does it appear that the area is free of potentially adverse seismic No spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Fire extinguishers on short hooks by MCCs - AR 2012-11669 was issued. Block wall behind 2-HV-AES-1 AND 2-HV-AES-2 - OK per DWG 12-4029, Wall W-7. 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? Yes 7. Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead

Location (Bldg, Elev, Room/Area):

Area 22 - AB2, 633, 8

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

George G Thomas Date: 10/18/12

Neda Stoeva

10/18/12




P9100203



P9100204

Location (Bldg, Elev, Room/Area): Area 22 - AB2, 633, 8





P9100205

P9100206

P9100209

Area 22 - AB2, 633, 8 Location (Bldg, Elev, Room/Area): P9100207 P9100208

P9100210

Status:	Y	N	П
olalus.	ı	IN	U

Loca	tion (Bldg, Elev, Room/Area): Area 23 - AB2, 587, 126			
Instru	ctions for Completing Checklist			
The sp	This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments.			
1.	Does anchorage of equipment in the area appear to be free of potentially adverse seismic conditions (if visible without necessarily opening cabinets)?	Yes		
2.	Does anchorage of equipment in the area appear to be free of significant degraded conditions?	Yes		
3.	Based on a visual inspection from the floor, do the cable/conduit raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)?	Yes		
4.	Does it appear that the area is free of potentially adverse seismic spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)?	Yes		
5.	Does it appear that the area is free of potentially adverse seismic interactions that could cause flooding or spray in the area?	Yes		
6.	Does it appear that the area is free of potentially adverse seismic interactions that could cause a fire in the area?	Yes		
7.	Does it appear that the area is free of potentially adverse seismic interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead shielding)?	Yes		

Location (Bldg, Elev, Room/Area):

Area 23 - AB2, 587, 126

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

Many M. George G Thomas Date: 10/18/12

Neda Stoeva

10/18/12





P9140527

Location (Bldg, Elev, Room/Area):

Area 23 - AB2, 587, 126



P9140529



P9140530



P9140531

Status: Y N U

Area Walk-By Checklist (AWC)

shielding)?

Location (Bldg, Elev, Room/Area): Area 24 - AB2, 587, 122 **Instructions for Completing Checklist** This checklist may be used to document the results of the Area Walk-By near one or more SWEL items. The space below each of the following questions may be used to record the results of judgments and findings. Additional space is provided at the end of this checklist for documenting other comments. 1. Does anchorage of equipment in the area appear to be free of Yes potentially adverse seismic conditions (if visible without necessarily opening cabinets)? 2. Does anchorage of equipment in the area appear to be free of Yes significant degraded conditions? 3. Based on a visual inspection from the floor, do the cable/conduit Yes raceways and HVAC ducting appear to be free of potentially adverse seismic conditions (e.g., condition of supports is adequate and fill conditions of cable trays appear to be inside acceptable limits)? 4. Does it appear that the area is free of potentially adverse seismic No spatial interactions with other equipment in the area (e.g., ceiling tiles and lighting)? Fire extinguishers on short hooks - AR 2012-11669 was issued. Block wall on left side of room - OK per DWG 2-4036, Wall W-1 and Wall-W2. 5. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause flooding or spray in the area? 6. Does it appear that the area is free of potentially adverse seismic Yes interactions that could cause a fire in the area? 7. Does it appear that the area is free of potentially adverse seismic Yes interactions associated with housekeeping practices, storage of portable equipment, and temporary installations (e.g., scaffolding, lead

Location (Bldg, Elev, Room/Area):

Area 24 - AB2, 587, 122

8. Have you looked for and found no other seismic conditions that could adversely affect the safety functions of the equipment in the area?

Yes

Comments

Evaluated by:

George G Thomas

Date: 10/18/12

Neda Stoeva

10/18/12









P9140541



Location (Bldg, Elev, Room/Area):

Area 24 - AB2, 587, 122

P9140542

P9140543



P9140544



P9140545



P9140546



P9140547



P9140548



P9140549

Location (Bldg, Elev, Room/Area):

Area 24 - AB2, 587, 122



P9140550





P9140552



P9140553

Location (Bldg, Elev, Room/Area): Area 24 - AB2, 587, 122



P9140554



P9140555



P9140556



P9140557



P9140558



P9140559

Location (Bldg, Elev, Room/Area): Area 24 - AB2, 587, 122





P9140560 P9140561