


CONTINUED  
NEXT PAGE

PSEG Power, LLC  
PSEG SITE ESPA  
Part 2, Site Safety Analysis Report

Boring Profile - NB-1  
FIGURE 2.5.4.7-1A  
REV 1



(Reference: 2.5.4.1-8)